





report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VVTI T SPIRIT
Colour	Blue
Year of manufacture	2006
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	150 Nm at 3.800 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	47.8 mpg
Consumption combined	40.3 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-18

Pictures 26

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-05
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	24
Total items failed	4

MOT #16		2023-08-03 09:57
MOT test i	number	351132567740
Result		✓ Passed
Next expir	ry date	2024-08-05
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (2))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Under body surface rust	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/13



Under body surface rust

Advice

WN56AWC

report date: 2024-03-28

MOT #15 2023-08-02 09:12 **MOT** test number 276795216009 Result × Failed Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Fail Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both sides (4.7.1 (b) (ii)) Fail Horn not working (7.7 (a)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14 2022-08-01 09:06

MOT test number 980153024747

Result ✓ Passed

MOT #13 2021-07-23 08:12

MOT test number 209500725167

•

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated weeping (6.1.7 (g) (i))

Advice All underside of vehicle corroded

CarCheck.co.uk page 4/13



Advice

WN56AWC

report date: 2024-03-28

MOT #12

MOT test number

854614379371

Result

Advice Nearside Front Inner driveshaft gater wiping

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11

MOT test number

Result

Advice Both headlamps deterated

2019-07-24 09:05

923396563116

✓ Passed

 MOT #10
 2018-07-20 11:07

 MOT test number
 121205559268

 Result
 ✓ Passed

 MOT #9
 2017-08-01 08:17

 MOT test number
 780214941237

 Result
 ✓ Passed

Hand brake effort 10% - both brakes locked

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #7	2015-07-20 13:11
MOT test number	185331005248
Result	✓ Passed
MOT #6	2014-07-18 10:59
MOT test number	969239094168
Result	✓ Passed
NOT #F	2012 00 05 11 20
MOT took number	2013-08-05 11:38
MOT test number	717557513298
Result	✓ Passed
MOT #4	2012-08-02 14:35
MOT test number	379105112238
Result	✓ Passed
MOT #3	2011-08-01 12:24
MOT test number	839883711220
Result	✓ Passed
MOT #2	2010-08-06 16:20
MOT test number	693598010283
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #1	2009-09-28 10:08
MOT test number	313191679402
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	5 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

\sim				
-()v	vner	hi	ะะก	ı۲
\sim v	V I C I		,,,,	

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

THE STREET STREE	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Correct registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13




report date: 2024-03-28

Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-09-27
Last registration	2023-08-03
Complete history	See info



Registration #1	2006-09-27	11 mi
Registration #2	2009-09-28	17.963 mi
Registration #3	2010-08-06	22.615 mi
Registration #4	2011-08-01	35.413 mi
Registration #5	2012-08-02	45.501 mi
Registration #6	2013-08-05	54.791 mi
Registration #7	2014-07-18	64.037 mi
Registration #8	2015-07-20	76.203 mi
Registration #9	2016-08-02	87.039 mi
Registration #10		11.777 es
Registration #11		9.79 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1220 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

Engine number 3ZZU778649