



report date: 2024-03-28

General information

Make	MAZDA
Model	5 D SPORT
Colour	Red
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 3

Date 2022-01-25

Pictures 4

Listing price [View report](#)




source: [autotrader.co.uk](#)

Entry 2

Date 2021-12-12

Pictures 5

Listing price [View report](#)





source: [autotrader.co.uk](#)

Entry 1

Date 2021-09-05

Pictures 18

Listing price [View report](#)



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-23
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	45
Total items failed	5

MOT #12	2023-10-18 14:12
MOT test number	578736628561
Result	✓ Passed
Next expiry date	2024-10-23
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #11	2022-10-21 12:06
MOT test number	537961913035
Result	✓ Passed
Advice	Oil leak
Advice	Vehicle fitted with under trays
Advice	Rear suspension arms/axle corroded

MOT #10	2021-10-21 08:40
MOT test number	376590925781
Result	✓ Passed
Advice	Tyre pressure monitoring system light on
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-10-24 16:41**MOT test number** 582018502029**Result** ✓ Passed

- Advice** Rear Anti-roll bar linkage ball joint has slight play both sides (5.3.4 (a) (i))
- Advice** Under covers fitted cant see all the components
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened and rear (1.1.14 (a) (ii))

MOT #8 2020-02-14 11:51**MOT test number** 480370616915**Result** ✓ Passed

- Advice** Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn Smooth Inner Edge (5.2.3 (e))
- Advice** Rear Anti-roll bar linkage ball joint has slight play Nearside and Offside (5.3.4 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive Engine/Gearbox Area (8.4.1 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect On Limit Now & Shroud Insecure (5.3.2 (b))
- Advice** Inner Sills Corroded
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #7**

2019-02-22 10:25

MOT test number

926385600687

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear wiper is deteriorating
- Advice** Exhaust heat shield is loose
- Advice** Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened & brake pads have worn more than the offside (1.1.14 (a) (ii))
- Advice** Oil residue engine area

MOT #6

2018-02-20 10:27

MOT test number

207220376809

Result

✓ Passed

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Nearside & offside rear tyres perishing
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
- Advice** Offside front wiper blade deteriorating
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside rear shock absorber dust cover deteriorating

**MOT #5** 2017-02-09 10:41**MOT test number** 495230473355**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #4** 2016-02-19 11:36**MOT test number** 497398607807**Result** ✓ Passed**MOT #3** 2015-03-03 12:03**MOT test number** 825782765091**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-03-04 13:58**MOT test number** 149603864454**Result** ✓ Passed**Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Notice** Nsr tyre tread surface slightly un-even on inner edge



MOT #1

2014-02-27 10:29

MOT test number

679398554002

Result		✗ Failed
Fail	Offside Rear Brake linkage has abnormal movement of levers indicating excessive wear (3.5.1f)	
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)	
Advice	Offside front brake fluctuating, but not excessively (3.7.B.3)	
Notice	Nsr tyre tread surface slightly un-even on inner edge	
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Advice	Offside Front Shock absorber has a light misting of oil (2.7.3)	
Fail	Parking brake lever has no reserve travel (3.1.6b)	



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
23 October 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-04
Last registration	2023-10-18
Complete history	See info



Registration #1	2011-03-04	23 mi
Registration #2	2014-02-27	42.689 mi
Registration #3	2014-03-04	42.849 mi
Registration #4	2015-03-03	55.452 mi
Registration #5	2016-02-19	67.268 mi
Registration #6	2017-02-09	79.044 mi
Registration #7	2018-02-20	88.175 mi
Registration #8	2019-02-22	95.024 mi
Registration #9	2020-05-20	95.024 mi
Registration #10	2020-05-20	95.024 mi
Registration #11	2020-05-20	95.024 mi
Registration #12	2020-05-20	95.024 mi
Registration #13	2020-05-20	95.024 mi
Registration #14	2020-05-20	95.024 mi
Registration #15	2020-05-20	95.024 mi
Registration #16	2020-05-20	95.024 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 325182