



PEUGEOT

BPO7YBR

report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 S
Colour	Silver
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	133 Nm at 3.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg






Internet history

Entry 1

Date	2021-06-29
Pictures	10
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #24	2023-06-02 15:06
MOT test number	372497239028
Result	✓ Passed
Next expiry date	2024-06-23
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Power steering component has slight seepage from a component (2.1.5 (a))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Central Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #23	2023-06-02 14:01
MOT test number	912761953412
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Central Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Fail	Power steering malfunctioning (2.1.5 (a))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

**MOT #22**

2022-06-16 13:34

MOT test number

229110359671

Result

✓ Passed

Advice Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #21**

2022-06-09 13:33

MOT test number

378816400065

Result

✗ Failed

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Nearside Rear Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**MOT #20**

2021-06-24 14:01

MOT test number

204501468882

Result

✓ Passed

**MOT #19** 2021-06-24 12:19**MOT test number** 965843534740**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #18** 2020-06-10 09:04**MOT test number** 356761018115**Result** ✓ Passed**MOT #17** 2019-06-14 11:06**MOT test number** 634099858402**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-06-14 08:31**MOT test number** 718928225349**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2018-06-04 12:17**MOT test number** 396601500459**Result** ✓ Passed**MOT #14** 2018-06-04 09:49**MOT test number** 793650369163**Result** ✗ Failed**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #13** 2017-06-09 08:29**MOT test number** 428875477350**Result** ✓ Passed**MOT #12** 2017-06-08 07:23**MOT test number** 892281840161**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Slight play offside inner rack joint**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #11** 2016-06-20 15:27**MOT test number** 287770332878**Result** ✓ Passed**MOT #10** 2015-07-21 10:29**MOT test number** 825002805275**Result** ✓ Passed

**MOT #9** 2014-07-24 14:54**MOT test number** 276095404209**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-07-21 10:43**MOT test number** 529162404232**Result** ✗ Failed**Fail** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Headlamp aim too low (1.8)**MOT #7** 2013-07-31 13:52**MOT test number** 276952013269**Result** ✓ Passed

**MOT #6** 2013-07-29 10:42**MOT test number** 648950113265**Result** ✗ Failed**Fail** Nearside Front Steering arm has relative movement at its fixings (2.2.B.1h)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front constant velocity joint is insecure (2.5.C.1b)**MOT #5** 2012-07-27 15:59**MOT test number** 978239402224**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #4** 2012-07-26 10:00**MOT test number** 297568702246**Result** ✗ Failed**Notice** Play in steering rack inner joint(s)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-07-27 15:27**MOT test number** 828238001248**Result** ✓ Passed**Advice** Nearside Front Steering pivot point has slight play (2.2.B.1g)**Advice** Offside Front Steering pivot point has slight play (2.2.B.1g)



MOT #2	2011-07-27 11:32
MOT test number	135518001228
Result	✗ Failed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Steering pivot point has slight play (2.2.B.1g)
Advice	Nearside Front Steering pivot point has slight play (2.2.B.1g)

MOT #1	2010-07-28 10:37
MOT test number	170299700269
Result	✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2007-08-30
Last registration	2023-06-02
Complete history	See info



Registration #1	2007-08-30	22 mi
Registration #2	2010-07-28	12.448 mi
Registration #3	2011-07-27	16.444 mi
Registration #4	2011-07-27	16.444 mi
Registration #5	2012-07-26	21.604 mi
Registration #6	2012-07-27	21.619 mi
Registration #7	2013-07-29	27.446 mi
Registration #8	2013-07-31	27.451 mi
Registration #9	2014-07-21	33.449 mi
Registration #10	2014-07-24	33.479 mi
Registration #11	2015-07-21	39.915 mi
Registration #12	2016-06-20	44.716 mi
Registration #13	2017-06-08	52.864 mi
Registration #14	2018-06-20	59.377 mi
Registration #15	2019-06-20	65.377 mi
Registration #16	2020-06-20	71.377 mi
Registration #17	2021-06-20	77.377 mi
Registration #18	2022-06-20	83.377 mi
Registration #19	2023-06-02	89.377 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		
Registration #24		
Registration #25		
Registration #26		

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1249 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FE040410910