



report date: 2024-03-29

General information

Make	BMW
Model	X5 D SPORT
Colour	Blue
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	30.1 mpg
CO2 emission	250 g/km
CO2 label	L





Internet history

Entry 2

Date	2021-10-02
Pictures	13
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-15
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	24
Total items failed	10

MOT #19 2024-01-16 09:12

MOT test number 541312959403

Result ✓ Passed

Next expiry date 2025-01-15

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement for most arm (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #18 2022-10-20 11:05

MOT test number 435450639708

Result ✓ Passed

Advice Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Front Lower Suspension component ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))

Advice Brake pipe corroded, covered in grease or other material OSF and Rears (1.1.11 (c))

**MOT #17**

2022-10-12 15:15

MOT test number

268001994591

Result

✗ Failed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Minor** Front Lower Suspension component ball joint dust cover severely deteriorated Both (5.3.4 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Electronic stability control switch not functioning correctly (7.12 (d))
- Advice** Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement Both (5.3.4 (a) (i))
- Advice** EML not illuminating
- Advice** Brake pipe corroded, covered in grease or other material OSF and Rears (1.1.11 (c))
- Fail** Nearside Front Tyre has ply or cords exposed outer wall (5.2.3 (d) (ii))
- Advice** Electronic stability control warning lamp not working (7.12 (e))

MOT #16

2021-10-01 12:54

MOT test number

699184132717

Result

✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15

2020-09-26 17:02

MOT test number

982276752123

Result

✓ Passed

- Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #14** 2019-10-01 16:22**MOT test number** 910990901664**Result** ✓ Passed**MOT #13** 2019-09-25 16:27**MOT test number** 500072572990**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #12** 2018-09-15 09:53**MOT test number** 954026210568**Result** ✓ Passed**Advice** Nearside Rear Outer Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #11** 2017-09-16 10:35**MOT test number** 917487009568**Result** ✓ Passed**MOT #10** 2016-09-24 08:42**MOT test number** 534476800647**Result** ✓ Passed

**MOT #9** 2016-09-24 08:42**MOT test number** 425947965603**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #8** 2015-09-16 11:23**MOT test number** 922567231009**Result** ✓ Passed**MOT #7** 2014-09-18 14:34**MOT test number** 485851564284**Result** ✓ Passed**Notice** Oil leak**MOT #6** 2014-09-18 11:02**MOT test number** 619261464269**Result** ✗ Failed**Notice** Oil leak**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #5** 2013-09-20 15:12**MOT test number** 127483963261**Result** ✓ Passed**MOT #4** 2012-09-20 19:50**MOT test number** 555544362230**Result** ✓ Passed



MOT #3	2011-09-23 16:23
MOT test number	718306761225
Result	✓ Passed

MOT #2	2010-09-20 12:45
MOT test number	214813560200
Result	✓ Passed

MOT #1	2009-09-22 16:49
MOT test number	833975169205
Result	✓ Passed

Notice N/s/f tyre is worn low on outer edge and also has a nail in the tread



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
15 January 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	EY56VTA
Plate since	2019-03-29
Current registration	EY56VTA
Plate since	2019-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-06
Last registration	2024-01-16
Complete history	See info



Registration #1	2006-09-06	9 mi
Registration #2	2009-09-22	27.195 mi
Registration #3	2010-09-20	35.799 mi
Registration #4	2011-09-23	44.130 mi
Registration #5	2012-09-20	51.704 mi
Registration #6	2013-09-20	58.952 mi
Registration #7	2014-09-18	66.327 mi
Registration #8	2014-09-18	66.331 mi
Registration #9	2015-09-16	73.454 mi
Registration #10	2016-09-24	79.486 mi
Registration #11	2016-09-24	79.486 mi
Registration #12	2017-09-20	85.518 mi
Registration #13	2018-09-18	91.550 mi
Registration #14	2019-09-16	97.582 mi
Registration #15	2020-09-14	103.614 mi
Registration #16	2021-09-12	109.646 mi
Registration #17	2022-09-10	115.678 mi
Registration #18	2023-09-08	121.710 mi
Registration #19	2024-01-16	127.742 mi
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1872 mm
Height	1740 mm
Length	4667 mm
Wheel base	2820 mm
Kerb weight	2180 kg
Max. allowed weight	2695 kg

Additional information

Fuel tank capacity	93 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	25426273