



General information

Make	FORD
Model	FIESTA ZETEC S
Colour	White
Year of manufacture	2010
Top speed	120 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	152 Nm at 4.050 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2024-09-09
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	65
Total items failed	10

MOT #19	2023-09-07 10:31
MOT test number	738368978216
Result	✓ Passed
Next expiry date	2024-09-09
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Nail in tyre 2mm

MOT #18	2023-09-02 10:45
MOT test number	856287513599
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Nail in tyre 2mm
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lights inop. (4.7.1 (b) (ii))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Nearside Front Steering linkage ball joint has excessive play inner tie rod (2.1.3 (b) (i))

**MOT #17**

2022-08-23 09:02

MOT test number

282218569153

Result

✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2021-09-10 15:07

MOT test number

833329439622

Result

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

**MOT #15**

2021-09-09 16:43

MOT test number

752382156814

Result**✗ Failed****MAJOR** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14**

2020-09-08 10:03

MOT test number

808317654123

Result**✓ Passed****Advice** Items removed from driver's view prior to test**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Coolant leak cooling fan not cutting in system pressure in expansion tank**Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

**MOT #13** 2019-08-05 13:18**MOT test number** 732814655054**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2019-08-03 09:26**MOT test number** 192219589897**Result** ✗ Failed**Advice** Vehicles internal headlight adjuster altered to recheck lights**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Items removed from driver's view prior to test**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Front Tyre obviously under inflated (5.2.3 (l))**MOT #11** 2018-03-08 13:11**MOT test number** 309690905467**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt small pin hole (2.5.C.1a)**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2018-03-08 10:05

MOT test number

893869313246

Result**✗ Failed**

Fail Nearside Rear Trailing arm rubber mounting deteriorated resulting in excessive movement axle (2.4.G.2)

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Trailing arm rubber mounting deteriorated resulting in excessive movement axle (2.4.G.2)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #9

2017-03-10 13:11

MOT test number

463424761902

Result**✓ Passed**

Advice Rear slight movement on rear registration plate not insecure

Advice Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

MOT #8

2017-03-09 15:19

MOT test number

865752837519

Result**✗ Failed**

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice Rear slight movement on rear registration plate not insecure

Fail Offside Registration plate lamp not working (1.1.C.1d)

Advice Offside Front Inner Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

**MOT #7** 2016-02-02 15:09**MOT test number** 785147815219**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #6** 2016-02-02 15:09**MOT test number** 435526069589**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #5** 2015-04-28 11:54**MOT test number** 345898415186**Result** ✓ Passed**MOT #4** 2015-04-28 08:39**MOT test number** 988928915142**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Front Road wheel bead rim badly distorted (4.2.A.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-04-15 15:12**MOT test number** 539665304113**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



MOT #2	2014-04-15 15:12
MOT test number	767125304162
Result	✗ Failed
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Pass with rectification	Nearside Stop lamp not working (1.2.1b)

MOT #1	2013-04-23 13:11
MOT test number	476123713129
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 September 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-30
Last registration	2023-09-07
Complete history	See info



Registration #1	2010-04-30	14 mi
Registration #2	2013-04-23	19.322 mi
Registration #3	2014-04-15	26.770 mi
Registration #4	2015-04-28	36.195 mi
Registration #5	2015-04-28	36.195 mi
Registration #6	2016-02-02	42.566 mi
Registration #7	2016-02-02	42.566 mi
Registration #8	2017-03-09	53.164 mi
Registration #9	2017-03-10	53.164 mi
Registration #10	2018-03-08	61.524 mi
Registration #11	2019-03-08	61.524 mi
Registration #12	2019-03-08	61.524 mi
Registration #13	2019-03-08	61.524 mi
Registration #14	2019-03-08	61.524 mi
Registration #15	2019-03-08	61.524 mi
Registration #16	2019-03-08	61.524 mi
Registration #17	2019-03-08	61.524 mi
Registration #18	2019-03-08	61.524 mi
Registration #19	2019-03-08	61.524 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3953 mm
Kerb weight	1109 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2

Engine number

AS39013