





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY
Colour	Black
Year of manufacture	2015
Top speed	151 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/11



GY15LFW

report date: 2024-03-29

Internet history

Entry 3

Date 2022-07-08

Pictures 29

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 2

Date	2021-10-23
Pictures	20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-07
Pictures	0
Listing price	<u>View report</u>

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-06-15
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	10
Total items failed	0

MOT #6		2023-06-16 13:32
MOT test	number	134512725651
Result		✓ Passed
Next expi	y date	2024-06-15
Advice	Front brake pads over half worn.	
Advice	Rear Tyre slightly damaged/cracking or perishing offside and nearside 245/40/	/17 (5.2.3 (d) (ii))

MOT #5	2022-07-21 11:48
MOT test number	780819791206
Result	✓ Passed

MOT #4		2021-08-16 12:27
MOT test	number	509571744039
Result		✓ Passed
Advice	Front Lower DRL lamps both not working	
Advice Offside Front Oil leak, but not excessive from turbo area causing smoke (8.4.1 (a) (i))		(a) (i))
Advice	Front Wheel bearing has slight play both sides have play but within tolerance (5.1.3 (a) (i))

CarCheck.co.uk page 3/11



MOT #3 2020-08-18 13:28

MOT test number 130567146005

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.1mm also cracking/perishing (5.2.3

(e))

Advice Front Lower Day time running lamps not working x2

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2019-08-08 09:07

MOT test number 850421667939

Result ✓ Passed

MOT #1 2018-08-22 10:22

MOT test number 244488093266

Result \rightarrow Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



GY15LFW

report date: 2024-03-29

More info >

Owner history

e which misterly	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	NIE.
Plate since	
Current registration	NK SIE
Plate since	m-o-o

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-07
Last registration	2023-06-16
Complete history	See info



Registration #1	2015-05-07	26 mi
Registration #2	2018-08-22	15.155 mi
Registration #3	2019-08-08	22.188 mi
Registration #4	2020-08-18	30.434 mi
Registration #5	2021-08-16	34.694 mi
_		
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
		1.77 m
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032659078

CarCheck.co.uk page 11/11