



RJ58YZB

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Blue
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	15.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	155 Nm at 1.600 rpm
Engine capacity	1.422 cc
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-01-29
Pictures	5
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-11-13
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	23
Total items failed	10

MOT #16 2023-11-14 09:10

MOT test number 847806635434

Result ✓ Passed

Next expiry date 2024-11-13

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Rear Exhaust silencer slightly loose exhaust back box deteriorated (8.1.1 (b) (i))

**Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #15 2023-11-11 13:37

MOT test number 361454511453

Result ✗ Failed

**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Advice** Nearside Rear Exhaust silencer slightly loose exhaust back box deteriorated (8.1.1 (b) (i))

**Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**Fail** Brake lever not releasing correctly and functionality of brakes affected (1.1.2 (b) (ii))

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))



MOT #14	2022-11-07 10:45
MOT test number	399122976077
Result	✓ Passed

MOT #13	2021-11-09 16:18
MOT test number	146344715184
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn edge and perished (5.2.3 (e))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing both rears perished (5.2.3 (d) (ii))
- Advice** Rear exhaust deteriorated
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn edge and perished (5.2.3 (e))

**MOT #12**

2021-11-09 10:08

**MOT test number**

138116419350

**Result****✗ Failed****Advice**

Items removed from driver's view prior to test

**Fail**

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge worn edge and perished (5.2.3 (e))

**Advice**

Rear exhaust deteriorated

**Advice**

Tyre slightly damaged/cracking or perishing both rears perished (5.2.3 (d) (ii))

**Fail**

Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail**

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge worn edge and perished (5.2.3 (e))

**Fail**

Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Fail**

Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Minor**

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail**

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11**

2020-10-30 17:45

**MOT test number**

797521270622

**Result****✓ Passed****Advice**

Rear Exhaust has a minor leak of exhaust gases REAR BOX (6.1.2 (a))

**Advice**

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10**

2019-10-14 13:03

**MOT test number**

942901874116

**Result****✓ Passed**

**MOT #9** 2018-11-05 12:41**MOT test number** 557137168366**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2017-10-26 14:53**MOT test number** 255064080606**Result** ✓ Passed**MOT #7** 2016-11-25 14:07**MOT test number** 619392615286**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2015-11-19 11:36**MOT test number** 823471990041**Result** ✓ Passed**MOT #5** 2015-11-18 14:25**MOT test number** 994354853329**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #4** 2014-11-14 12:30**MOT test number** 355758714342**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #3	2013-11-04 14:04
MOT test number	955738803338
Result	✓ Passed
MOT #2	2012-11-07 16:35
MOT test number	405462412334
Result	✓ Passed
MOT #1	2011-11-15 14:19
MOT test number	775009311313
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
13 November 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	13 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>RJ58YZB</b>
Plate since	2024-03-28
Current registration	 <b>RJ58YZB</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-11-28
Last registration	2023-11-14
Complete history	<a href="#">See info</a>



Registration #1	2008-11-28	28 mi
Registration #2	2011-11-15	10.299 mi
Registration #3	2012-11-07	13.521 mi
Registration #4	2013-11-04	17.253 mi
Registration #5	2014-11-14	21.453 mi
Registration #6	2015-11-18	25.130 mi
Registration #7	2015-11-19	25.140 mi
Registration #8	2016-11-25	30.571 mi
Registration #9	2017-10-26	34.863 mi
Registration #10	2018-11-28	39.155 mi
Registration #11	2019-11-28	43.447 mi
Registration #12	2020-11-28	47.739 mi
Registration #13	2021-11-28	52.031 mi
Registration #14	2022-11-28	56.323 mi
Registration #15	2023-11-28	60.615 mi
Registration #16	2024-11-28	64.907 mi
Registration #17	2025-11-28	69.199 mi
Registration #18	2026-11-28	73.491 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5

**Number of axles**

2

**Engine number**

BNM317137