






report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE V6 SPORT
Colour	Black
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-06-16

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT #19 2021-07-23 10:15

MOT test number 546682360279

Result

Passed

Next expiry date 2022-07-22

Advice General underbody/pipes/ferulles/springs corroded

Advice Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18 2020-10-14 13:08

MOT test number 238984067328

Result
✓ Passed

Advice Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Play in steering rack inner joint(s)

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #17 2019-10-07 09:57

MOT test number 679139128992

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 3/14



MOT #16 2018-10-08 16:19

MOT test number 314062964366

Result ✓ Passed

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #15 2018-10-08 14:27

MOT test number 291789399490

Result X Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #14 2017-10-16 10:45

MOT test number 599147733882

Result \rightarrow Passed

MOT #13 2016-10-18 12:42

MOT test number 558167837307

MOT #12 2016-10-17 13:03

MOT test number 228935501186

Result X Failed

Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)

Advice Grease leak from front propshaft joint

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

CarCheck.co.uk page 4/14



MOT #11 2015-10-08 10:26

MOT test number 448867515909

Result
✓ Passed

Advice Engine covers fitted obscuring view of components

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10 2015-10-06 15:21

MOT test number 972959525469

Result X Failed

Fail Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Oil leak

Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Engine covers fitted obscuring view of components

MOT #9 2014-10-15 15:50

MOT test number 136988184219

CarCheck.co.uk page 5/14



BJ07KRF

report date: 2024-03-29

MOT #8 2014-10-14 14:12

MOT test number 685657084252

Result X Failed

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)

MOT #7 2013-10-16 09:59

MOT test number 698569183210

Result
✓ Passed

Notice Oil leak

Advice Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #6 2013-10-15 16:31

MOT test number 307598583275

Result X Failed

Advice Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Oil leak

Fail

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #5 2012-10-12 11:20

MOT test number 885026982268

Result \rightarrow Passed

CarCheck.co.uk page 6/14



MOT #4 2011-10-18 16:00

MOT test number 326651891241

Result ✓ Passed

MOT #3 2011-06-13 11:31

MOT test number 408644161110

Advice Offside Front Front suspension has slight movement at a suspension ball joint (2.5.A.1c)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Suspension joint offside lower dust cover split/missing

MOT #2 2011-06-13 11:31

MOT test number 926744661182

Result X Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Notice Suspension joint offside lower dust cover split/missing

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Front suspension has slight movement at a suspension ball joint (2.5.A.1c)

CarCheck.co.uk page 7/14



MOT #1 2010-07-10 08:33
MOT test number 541681090141

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice N/s/f door mirror cover missing

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-29
Last registration	2021-07-23
Complete history	See info



Registration #1	2007-03-29	15 mi
Registration #2	2010-07-10	24.369 mi
Registration #3	2011-06-13	27.100 mi
Registration #4	2011-10-18	28.988 mi
Registration #5	2012-10-12	32.864 mi
Registration #6	2013-10-15	40.300 mi
Registration #7	2013-10-16	40.300 mi
Registration #8	2014-10-14	47.239 mi
Registration #9	2014-10-15	47.239 mi
Registration #10	2015-10-06	52.168 mi
Registration #11		0.777 es
Registration #12		11.777 es
Registration #13		9.79 es
Registration #14		11.777 es
Registration #15		9.79 es
Registration #16		11.777 es
Registration #17		9.79 es
Registration #18		11.777 es
Registration #19		D.777 es
Registration #20		n.m.

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	548873414XB

CarCheck.co.uk page 14/14