




General information

Make	CITROEN
Model	XSARA SX HDI PICASSO
Colour	Green
Year of manufacture	2001
Top speed	109 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.900 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-12-24
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-18
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	40
Total items failed	15

MOT #24	2024-03-19 11:22
MOT test number	425120501183
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #23	2023-01-31 17:22
MOT test number	582825680778
Result	✓ Passed
Advice	Offside Direction indicator slightly discoloured Side Repeater (4.4.3 (a))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #22**

2023-01-23 15:55

**MOT test number**

691883203868

**Result****✗ Failed****Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Rear Exhaust has a major leak of exhaust gases Back Box (6.1.2 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Direction indicator slightly discoloured Side Repeater (4.4.3 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #21**

2022-01-05 17:32

**MOT test number**

374342701791

**Result****✓ Passed****Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2021-12-24 15:51**MOT test number** 562672461056**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19** 2021-01-28 14:13**MOT test number** 683905012828**Result** ✓ Passed**MOT #18** 2021-01-27 12:21**MOT test number** 789767825052**Result** ✗ Failed**Fail** Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #17** 2020-01-27 11:45**MOT test number** 297684803179**Result** ✓ Passed**MOT #16** 2019-01-23 12:47**MOT test number** 163866065908**Result** ✓ Passed

**MOT #15** 2019-01-22 10:54**MOT test number** 620605473645**Result** ✗ Failed

- Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail Rear Exhaust system insecure (6.1.2 (a))
- Fail Offside Front Valve stem seriously misaligned (5.2.3 (j))
- Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #14** 2018-01-24 15:15**MOT test number** 387203598168**Result** ✓ Passed

- Advice Child Seat fitted not allowing full inspection of adult belt both rear seats
- Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #13** 2018-01-23 10:17**MOT test number** 947093962863**Result** ✗ Failed

- Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice Child Seat fitted not allowing full inspection of adult belt both rear seats
- Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

**MOT #12** 2017-01-27 10:08**MOT test number** 323258936342**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust mountings corroded**MOT #11** 2016-01-26 11:23**MOT test number** 434284865666**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #10** 2015-01-27 15:15**MOT test number** 339767525096**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #9** 2015-01-27 10:03**MOT test number** 159527125434**Result** ✗ Failed**Fail** Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2014-01-28 10:37**MOT test number** 306208424036**Result** ✓ Passed



<b>MOT #7</b>	2013-01-28 10:36
---------------	------------------

<b>MOT test number</b>	297318923031
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2012-01-27 12:17
---------------	------------------

<b>MOT test number</b>	348417522044
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2011-01-27 09:39
---------------	------------------

<b>MOT test number</b>	247907621086
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2010-01-26 09:48
---------------	------------------

<b>MOT test number</b>	282156920049
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2009-01-27 11:36
---------------	------------------

<b>MOT test number</b>	734987229021
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Exhaust has a minor leak of exhaust gases (7.1.2)
---------------	---------------------------------------------------

<b>MOT #2</b>	2008-01-12 09:02
---------------	------------------

<b>MOT test number</b>	811822918011
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Front Brake pad(s) wearing thin (3.5.1g)
---------------	---------------------------------------------------

<b>Advice</b>	Centre Exhaust has a minor leak of exhaust gases (7.1.2)
---------------	----------------------------------------------------------

<b>Advice</b>	Offside Front Brake pad(s) wearing thin (3.5.1g)
---------------	--------------------------------------------------



MOT #1	2007-01-25 13:31
MOT test number	723025027015
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
18 March 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	18 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-09-21
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2001-09-21	26 mi
Registration #2	2007-01-25	29.482 mi
Registration #3	2008-01-12	31.364 mi
Registration #4	2009-01-27	34.366 mi
Registration #5	2010-01-26	36.405 mi
Registration #6	2011-01-27	37.756 mi
Registration #7	2012-01-27	38.701 mi
Registration #8	2013-01-28	40.673 mi
Registration #9	2014-01-28	42.271 mi
Registration #10	2015-01-27	43.697 mi
Registration #11	2015-01-27	43.697 mi
Registration #12	2016-01-26	45.212 mi
Registration #13	2017-01-27	47.041 mi
Registration #14	2018-01-27	48.377 mi
Registration #15	2019-01-27	49.713 mi
Registration #16	2020-01-27	51.049 mi
Registration #17	2021-01-27	52.385 mi
Registration #18	2022-01-27	53.721 mi
Registration #19	2023-01-27	55.057 mi
Registration #20	2024-01-27	56.393 mi
Registration #21	2025-01-27	57.729 mi
Registration #22	2026-01-27	59.065 mi
Registration #23	2027-01-27	60.401 mi
Registration #24	2028-01-27	61.737 mi
Registration #25	2029-01-27	63.073 mi
Registration #26	2030-01-27	64.409 mi

**More info** >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DYKG3001916