





report date: 2024-03-29

#### General information

Make	MERCEDES-BENZ
Model	E E 220 D AMG LINE PREMIUM PLUS
Colour	Grey
Year of manufacture	2018
Top speed	150 mph
0 - 100 km/h	7.4 seconds
0 - 60 mph	7.7 seconds
Gearbox	9 speed automatic

## Engine & fuel consumption

Power	143 kW / 195 HP / 191 BHP
Max. torque	400 Nm at 1.600 rpm
Engine capacity	1.950 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 2


Date 2022-02-24

Pictures 39

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2022-01-18
-----------------

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## **MOT** history

MOT expiry date	2024-06-29
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #6		2023-06-30 12:26
MOT test	number	166203690030
Result		✓ Passed
Next expi	ry date	2024-06-29
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))	
Advice	Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Nail in tyre	

CarCheck.co.uk page 3/12



GV18TLO report date: 2024-03-29

**MOT #5** 2023-06-26 09:43

**MOT test number** 751089417880

Result × Failed

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both rear (1.1.14 (a) (ii))

**Advice** Offside Rear Nail in tyre

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Inner Road wheel fractured (5.2.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2022-05-31 07:43

**MOT test number** 414747752362

**Result** ✓ Passed

MOT #3 2022-02-07 16:46

**MOT test number** 210861012412

**Result** ✓ Passed

**MOT #2** 2022-02-02 10:31

MOT test number 129880929237

**Result** ★ Failed

Fail Nearside Rear Road wheel fractured (5.2.2 (a))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2021-06-24 10:42

**MOT test number** 527240477392

Result Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake servo hose supporting rubber mount through plenum fire wall broken away.not supporting

hose allowing it to rub

CarCheck.co.uk page 5/12



GV18TLO report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 June 2024
Full MOT history	See MOT history

#### Tax calculation

1 10 10 10 1	
Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date
Category

Damage 2

**Type** 

Date

Category

**Type** 



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



GV18TLO report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



GV18TLO report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MERCEDES-BENZ had different number plates. mber of plates -More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



GV18TLO report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-06-29
Last registration	2023-06-30
Complete history	See info



Registration #1	2018-06-29	27 mi
Registration #2	2021-06-24	30.661 mi
Registration #3		11.777 es
Registration #4	2022-02-02	36.507 mi
Registration #5	2022-02-07	36.507 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		

More info >

CarCheck.co.uk page 11/12



GV18TLO report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	
iew the complete MERCEDES-BENZ factory list for this	More info >

# Dimensions & weight

Width	1860 mm
Height	1430 mm
Length	4826 mm
Wheel base	2939 mm
Kerb weight	1730 kg
Max. allowed weight	2300 kg

## Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	65492080208527

CarCheck.co.uk page 12/12