



report date: 2024-03-29

General information

Make	KIA
Model	SOUL TEMPEST
Colour	Cream
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-13
Pictures	27
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	27
Total items failed	7

MOT #16	2023-08-08 16:00
MOT test number	829189425499
Result	✓ Passed
Next expiry date	2024-08-10
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer edge perished. (5.2.3 (d) (i))

MOT #15	2023-08-08 09:09
MOT test number	833888624646
Result	✗ Failed
Fail	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Rear Brake pipe excessively corroded Both sides (1.1.11 (c))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords Outer edge perished. (5.2.3 (d) (i))

MOT #14	2022-07-29 10:06
MOT test number	612821132691
Result	✓ Passed
Advice	Oil leak, but not excessive very slight (8.4.1 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13** 2022-07-29 10:06**MOT test number** 669202192733**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive very slight (8.4.1 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Steering locking device missing track rod end (2.1.3 (d))**MOT #12** 2021-08-11 12:13**MOT test number** 337675263457**Result** ✓ Passed**MOT #11** 2021-08-11 09:48**MOT test number** 121286223047**Result** ✗ Failed**Fail** Nearside Front Position lamp not working bulb flashing (4.2.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2020-10-22 11:59

MOT test number

269037723300

Result

✓ Passed

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #9

2019-07-23 08:09

MOT test number

640695969837

Result

✓ Passed

MOT #8

2019-07-22 10:49

MOT test number

385425853308

Result

✗ Failed

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #7

2018-07-27 11:43

MOT test number

935578224711

Result

✓ Passed

**MOT #6** 2017-07-28 10:50**MOT test number** 272463813769**Result** ✓ Passed**Advice** Offside Front tyre at 3 mm of tread**Advice** Nearside Front tyre at 3 mm of tread**Advice** Nearside Rear tyre at 2 mm of tread**MOT #5** 2016-08-01 11:36**MOT test number** 844407264191**Result** ✓ Passed**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #4** 2015-08-24 14:32**MOT test number** 680351591686**Result** ✓ Passed**MOT #3** 2015-08-24 14:32**MOT test number** 777764661184**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2014-09-03 15:45**MOT test number** 395936244263**Result** ✓ Passed



MOT #1	2013-09-06 12:06
MOT test number	398989143415
Result	✓ Passed
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Items removed from driver's view prior to test
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
10 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	10 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YG60ELH
Plate since	2019-09-29
Current registration	YG60ELH
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-17
Last registration	2023-08-08
Complete history	See info



Registration #1	2010-09-17	9 mi
Registration #2	2013-09-06	29.758 mi
Registration #3	2014-09-03	39.617 mi
Registration #4	2015-08-24	49.001 mi
Registration #5	2015-08-24	49.001 mi
Registration #6	2016-08-01	58.463 mi
Registration #7	2017-07-28	67.011 mi
Registration #8	2018-07-27	76.543 mi
Registration #9	2019-07-22	82.973 mi
Registration #10	2020-08-01	90.001 mi
Registration #11	2021-08-01	99.001 mi
Registration #12	2022-08-01	108.001 mi
Registration #13	2023-08-01	117.001 mi
Registration #14	2024-08-01	126.001 mi
Registration #15	2025-08-01	135.001 mi
Registration #16	2026-08-01	144.001 mi
Registration #17	2027-08-01	153.001 mi
Registration #18	2028-08-01	162.001 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1245 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCAH482176