



General information

Make	AUDI
Model	A6 AVANT TDI LE MANS
Colour	Blue
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	152 g/km
CO2 label	G





MOT history

MOT expiry date	2025-02-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	30
Total items failed	6

MOT #15	2024-02-08 16:33
MOT test number	700175546122
Result	✓ Passed
Next expiry date	2025-02-16

MOT #14	2023-02-17 09:24
MOT test number	220963295253
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both inner edges (5.2.3 (e))
Advice	Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #13	2022-12-01 09:27
MOT test number	635324629723
Result	✗ Failed
Fail	Offside Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Offside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
Advice	Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear both tyres wearing on the inner edges
Fail	Central Rear Seat belt buckle not functioning as intended does not release under tension (7.1.2 (d))
Advice	Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #12	2021-11-27 09:01
MOT test number	321454300893
Result	✓ Passed
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #11	2021-11-13 10:03
MOT test number	878790232204
Result	✗ Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2020-11-04 13:06
MOT test number	845925810194
Result	✓ Passed
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9	2019-11-07 11:56
MOT test number	627190299430
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #8	2018-11-10 10:23
MOT test number	471149639633
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))



MOT #7

2017-11-16 09:46

MOT test number

379722303093

Result

✓ Passed

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Advice

Under trays fitted preventing examination of some componants

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Advice

Engine bay cover(s) fitted preventing examination of some componants

Advice

Nearside front tyre worn on the inner edge

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

MOT #6

2017-11-08 11:58

MOT test number

571388432281

Result

✗ Failed

Advice

Engine bay cover(s) fitted preventing examination of some componants

Fail

Offside Front coil spring broken (2.4.C.1a)

Advice

Nearside front tyre worn on the inner edge

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Advice

Offside Rear brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Fail

Nearside Front coil spring broken (2.4.C.1a)

Advice

Under trays fitted preventing examination of some componants

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened worn (3.5.1i)

**MOT #5** 2016-11-17 15:04**MOT test number** 817815675154**Result** ✓ Passed**Advice** Full engine & body undertrays fitted**Advice** Plastic trim partly covering outer sills**MOT #4** 2015-11-10 12:47**MOT test number** 592894802469**Result** ✓ Passed**Advice** Engine and underside covers fitted**MOT #3** 2014-11-24 15:18**MOT test number** 339818024352**Result** ✓ Passed**MOT #2** 2014-03-20 14:52**MOT test number** 388689374059**Result** ✓ Passed**MOT #1** 2013-03-20 15:11**MOT test number** 527799473047**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 February 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-25
Last registration	2024-02-08
Complete history	See info



Registration #1	2010-03-25	24 mi
Registration #2	2013-03-20	66.398 mi
Registration #3	2014-03-20	79.931 mi
Registration #4	2014-11-24	90.029 mi
Registration #5	2015-11-10	101.008 mi
Registration #6	2016-11-17	112.171 mi
Registration #7	2017-11-08	121.096 mi
Registration #8	2017-11-16	121.179 mi
Registration #9	2019-05-20	121.179 mi
Registration #10	2019-05-20	121.179 mi
Registration #11	2019-05-20	121.179 mi
Registration #12	2019-05-20	121.179 mi
Registration #13	2019-05-20	121.179 mi
Registration #14	2019-05-20	121.179 mi
Registration #15	2019-05-20	121.179 mi
Registration #16	2019-05-20	121.179 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4927 mm
Wheel base	2843 mm
Kerb weight	1635 kg
Max. allowed weight	2265 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

CAH 136897