



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Grey
Year of manufacture	2007
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	143 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	182 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-07-20
Pictures	15
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-17
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	45
Total items failed	15

MOT #18	2023-10-18 12:22
---------	------------------

MOT test number	181545175690
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-17
------------------	------------

Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Upper Steering column universal joint has slight wear or play steering column joint (2.2.2 (c))
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))



MOT #17	2022-10-18 10:10
MOT test number	489442552232
Result	✓ Passed

MOT #16	2021-07-14 14:20
MOT test number	267808133459
Result	✓ Passed
<div><div>Advice</div>Wipers worn</div> <div><div>Advice</div>Exhaust front flexy failing</div>	

MOT #15	2020-07-21 09:54
MOT test number	555012844569
Result	✓ Passed

**MOT #14**

2020-07-20 13:49

MOT test number

200044577298

Result**✗ Failed**

- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect Bulb/lens opaque (4.1.2 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Wipers worn
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Brake pipe excessively corroded Front to rear at rear (1.1.11 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #13** 2019-07-09 13:45**MOT test number** 610239629655**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2018-07-17 13:34**MOT test number** 991117535632**Result** ✓ Passed**MOT #11** 2017-07-21 11:55**MOT test number** 728703542480**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #10** 2016-07-11 12:48**MOT test number** 373138388844**Result** ✓ Passed

**MOT #9** 2015-07-13 12:06**MOT test number** 287954995125**Result** ✓ Passed

- Notice** Exhaust corroded
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8 2015-07-08 09:53**MOT test number** 256369085442**Result** ✗ Failed

- Fail** Nearside Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Exhaust corroded
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #7 2014-07-04 11:17**MOT test number** 316935284180**Result** ✓ Passed

**MOT #6** 2014-07-03 12:43**MOT test number** 659244684132**Result** ✗ Failed**Fail** Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #5** 2013-07-05 12:49**MOT test number** 688366183168**Result** ✓ Passed**MOT #4** 2012-07-10 11:33**MOT test number** 598252992100**Result** ✓ Passed**MOT #3** 2012-07-06 11:24**MOT test number** 696388082169**Result** ✗ Failed**Fail** Nearside front brake binding (3.7.B.1)**Fail** Offside rear brake binding (3.7.B.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Headlamp aim too high (1.8)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #2** 2011-07-08 16:49**MOT test number** 195749081156**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front discs inner section worn and pitted



MOT #1	2010-05-21 10:07
MOT test number	234381340174
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 October 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	17 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YY07VFT
Plate since	2019-09-28
Current registration	YY07VFT
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-06-29
Last registration	2023-10-18
Complete history	See info



Registration #1	2007-06-29	18 mi
Registration #2	2010-05-21	19.126 mi
Registration #3	2011-07-08	22.194 mi
Registration #4	2012-07-06	24.163 mi
Registration #5	2012-07-10	24.163 mi
Registration #6	2013-07-05	27.661 mi
Registration #7	2014-07-03	30.469 mi
Registration #8	2014-07-04	30.469 mi
Registration #9	2015-07-08	32.053 mi
Registration #10	2015-07-13	32.086 mi
Registration #11	2016-06-29	35.277 mi
Registration #12	2016-06-29	35.277 mi
Registration #13	2016-06-29	35.277 mi
Registration #14	2016-06-29	35.277 mi
Registration #15	2016-06-29	35.277 mi
Registration #16	2016-06-29	35.277 mi
Registration #17	2016-06-29	35.277 mi
Registration #18	2016-06-29	35.277 mi
Registration #19	2016-06-29	35.277 mi
Registration #20	2016-06-29	35.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1256 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4ED7676195