



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Silver
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 3


Date	2021-09-30
Pictures	41
Listing price	View report



source: autotrader.co.uk

Entry 2

Date	2021-08-22
Pictures	32
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-08-13
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	38
Total items failed	13

MOT #15	2023-11-03 14:45
MOT test number	582401322812
Result	✓ Passed
Next expiry date	2024-11-02
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #14	2023-10-27 11:24
MOT test number	156328838217
Result	✗ Failed
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #13**

2022-10-11 16:07

MOT test number

124418582865

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12

2022-10-07 13:49

MOT test number

416373504788

Result

✗ Failed

- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Central Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Front Windscreen washer not working (3.5 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Front Windscreen washer not working (3.5 (a))

**MOT #11** 2021-09-03 10:42**MOT test number** 323961818359**Result** ✓ Passed**Advice** Engine cover missing**Advice** Covers / trays fitted**MOT #10** 2020-09-01 07:53**MOT test number** 852587785315**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear exhaust heat shield loose**MOT #9** 2019-08-30 16:19**MOT test number** 360573204589**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2019-08-30 08:19

MOT test number

214579553825

Result**✗ Failed**

- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #7

2018-08-23 11:09

MOT test number

260046115025

Result**✓ Passed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2017-08-29 11:43**MOT test number** 721871677587**Result** ✓ Passed

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Oil leak

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

MOT #5 2016-08-18 16:03**MOT test number** 414747641387**Result** ✓ Passed**MOT #4** 2016-08-18 08:19**MOT test number** 450614247494**Result** ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

MOT #3 2015-08-04 14:49**MOT test number** 666458833588**Result** ✓ Passed**MOT #2** 2014-09-02 11:49**MOT test number** 138705844233**Result** ✓ Passed



MOT #1	2013-09-03 08:59
MOT test number	367156143213
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-01
Last registration	2023-11-03
Complete history	See info



Registration #1	2010-03-01	17 mi
Registration #2	2013-09-03	44.088 mi
Registration #3	2014-09-02	55.477 mi
Registration #4	2015-08-04	65.652 mi
Registration #5	2016-08-18	74.920 mi
Registration #6	2016-08-18	74.920 mi
Registration #7	2017-08-29	84.368 mi
Registration #8	2018-08-23	92.617 mi
Registration #9	2019-08-30	98.796 mi
Registration #10	2019-08-30	98.796 mi
Registration #11	2019-08-30	98.796 mi
Registration #12	2019-08-30	98.796 mi
Registration #13	2019-08-30	98.796 mi
Registration #14	2019-08-30	98.796 mi
Registration #15	2019-08-30	98.796 mi
Registration #16	2019-08-30	98.796 mi
Registration #17	2019-08-30	98.796 mi
Registration #18	2019-08-30	98.796 mi
Registration #19	2019-08-30	98.796 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602