




report date: 2024-11-08

General information

Make	MINI
Model	COOPER D LONDON 2012 EDITION COOPER D
Colour	Red
Year of manufacture	2012
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2023-02-02
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-12-20
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	21
Total items failed	10

MOT #15	2024-12-06 16:05
MOT test number	367528649992
Result	✓ Passed
Next expiry date	2025-12-20

MOT #14	2024-12-06 15:10
MOT test number	634499352085
Result	✗ Failed
Fail	Offside Windscreen washer not working (3.5 (a))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13	2024-12-06 10:55
MOT test number	423854169576
Result	✗ Failed
Fail	Offside Windscreen washer not working (3.5 (a))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2023-12-21 11:41
MOT test number	316498872873
Result	✓ Passed



MOT #11 2023-12-20 10:39

MOT test number 330277397001

Result ✗ Failed

- Fail** Offside Front Suspension arm pin or bush excessively worn lower arm inner front bush (5.3.4 (a) (i))
- Fail** Nearside Front Body component likely to become detached inner front wing arch liner (6.2.1 (a) (ii))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm inner front bush (5.3.4 (a) (i))
- Fail** Central Front Undertray likely to become detached (6.2.1 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10 2022-12-07 17:28

MOT test number 652222878932

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Inner Suspension arm ball joint has slight play (5.3.4 (a) (i))



MOT #9	2022-12-07 11:24
MOT test number	196921277543
Result	✗ Failed
Advice	Offside Front Inner Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Front Outer Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Nail in tyre
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Front Anti-roll bar pin or bush worn but not resulting in excessive movement both (5.3.4 (a) (i))

MOT #8	2021-12-01 11:49
MOT test number	951573760876
Result	✓ Passed
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Inner wall (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Play in steering rack inner joint(s)

MOT #7	2020-11-30 13:13
MOT test number	933923710456
Result	✓ Passed

MOT #6	2019-06-12 12:55
MOT test number	837233693156
Result	✓ Passed



MOT #5	2019-06-11 08:38
MOT test number	222856529867
Result	✗ Failed
Fail	Offside Front Shock absorbers has a serious fluid leak has excessive movement (5.3.2 (b))
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #4	2018-06-02 09:34
MOT test number	105521591470
Result	✓ Passed

MOT #3	2017-05-27 12:31
MOT test number	224129689474
Result	✓ Passed

MOT #2	2016-06-01 14:48
MOT test number	850812671084
Result	✓ Passed
Advice	REAR TYRES SLIGHTLY OUT OF SHAPE PLUS CRACKING BETWEEN TREAD

MOT #1	2015-05-28 11:49
MOT test number	247638745448
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
20 December 2025

Tax status	Valid until 1 April
Days left	113
MOT expiry date	20 December 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	




Damage 2

Date	
Category	
Type	



Extra MINI salvage check

 If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YX12 HFM
Plate since	2019-09-29
Current registration	YX12 HFM
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-06-08
Last registration	2024-12-06
Complete history	See info



Registration #1	2012-06-08	28 mi
Registration #2	2015-05-28	23.745 mi
Registration #3	2016-06-01	30.879 mi
Registration #4	2017-05-27	36.987 mi
Registration #5	2018-06-02	42.251 mi
Registration #6	2019-06-11	57.733 mi
Registration #7	2019-06-12	57.733 mi
Registration #8	2020-11-30	66.895 mi
Registration #9	2021-12-01	85.574 mi
Registration #10	2022-05-27	95.277 mi
Registration #11	2022-05-27	95.277 mi
Registration #12	2022-05-27	95.277 mi
Registration #13	2022-05-27	95.277 mi
Registration #14	2022-05-27	95.277 mi
Registration #15	2022-05-27	95.277 mi
Registration #16	2022-05-27	95.277 mi
Registration #17	2022-05-27	95.277 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	70817962