



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Blue
Year of manufacture	2008
Top speed	109 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	131 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-07-21
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	49
Total items failed	25

MOT #21	2023-08-04 13:44
MOT test number	464557986321
Result	✓ Passed
Next expiry date	2024-08-03

MOT #20	2023-08-02 13:30
MOT test number	582706269360
Result	✗ Failed

- Fail

Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail

Nearside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
- Fail

Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))



MOT #19

2022-08-03 13:18

MOT test number

966956469738

Result

✓ Passed

- Advice

Rear Brake pipe corroded, covered in grease or other material both next to the fuel tank (1.1.11 (c))
- Advice

Hand brake cable bracket corroded and broken
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Rear beam axle corroded
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

General corrosion under vehicle
- Advice

Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #18**

2022-08-01 12:04

**MOT test number**

417716005018

**Result****✗ Failed****Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake pipe corroded, covered in grease or other material both next to the fuel tank (1.1.11 (c))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** General corrosion under vehicle**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Hand brake cable bracket corroded and broken**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Headlamp insecure (4.1.1 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Direction indicator likely to become detached wing (4.4.1 (c) (ii))**Advice** Rear beam axle corroded**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #17**

2021-07-21 14:12

**MOT test number**

237121665663

**Result****✓ Passed****Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #16**

2021-07-15 13:46

**MOT test number**

211045498361

**Result****✗ Failed**

- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))
- Fail** Rear Brake pipe excessively corroded across axle (1.1.11 (c))
- Fail** Brake lever has insufficient reserve travel (1.1.2 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Fail** Offside Front Lower Anti-roll bar linkage ball joint excessively worn ball joint (5.3.4 (a) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #15**

2020-08-04 12:09

**MOT test number**

339727812190

**Result****✓ Passed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2020-08-01 08:30

**MOT test number**

396516238252

**Result****✗ Failed****Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13**

2019-04-01 16:29

**MOT test number**

795316732717

**Result****✓ Passed****Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**MOT #12**

2019-04-01 10:40

**MOT test number**

575051081530

**Result****✗ Failed****Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2018-03-29 10:56**MOT test number** 287043344658**Result** ✓ Passed**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #10** 2017-03-31 11:41**MOT test number** 546000459177**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases gasket (7.1.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tie bar/rod has slight play in a ball joint drop link (2.4.G.2)**MOT #9** 2016-03-21 11:53**MOT test number** 676803924364**Result** ✓ Passed**MOT #8** 2015-03-31 13:03**MOT test number** 858380095064**Result** ✓ Passed**MOT #7** 2014-04-17 13:51**MOT test number** 457037904139**Result** ✓ Passed





<b>MOT #6</b>	2013-05-04 10:49
<b>MOT test number</b>	815344923100
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

<b>MOT #5</b>	2013-04-22 17:33
<b>MOT test number</b>	746292713157
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Offside Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Fail</b>	Nearside Front coil spring incomplete (2.4.C.1a)

<b>MOT #4</b>	2012-04-30 15:54
<b>MOT test number</b>	436271522125
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2012-04-30 13:07
<b>MOT test number</b>	867381722185
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Fail</b>	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
<b>Fail</b>	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2011-05-05 12:35
MOT test number	965425521175
Result	✓ Passed

MOT #1	2011-05-05 12:35
MOT test number	665745621149
Result	✗ Failed

Pass with rectification

 Front Windscreen washer provides insufficient washer liquid (8.2.3)



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2024

✓

MOT

Expires:  
3 August 2024

Tax status	Expired at 1 April 2024
Days left	28 days too late
MOT expiry date	3 August 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXX XX</b>
Plate since	2024-03-29
Current registration	 <b>XXXX XX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-07
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2008-05-07	9 mi
Registration #2	2011-05-05	22.070 mi
Registration #3	2012-04-30	26.327 mi
Registration #4	2012-04-30	26.327 mi
Registration #5	2013-04-22	31.831 mi
Registration #6	2013-05-04	31.831 mi
Registration #7	2014-04-17	34.839 mi
Registration #8	2015-03-31	39.932 mi
Registration #9	2016-03-21	44.726 mi
Registration #10	2017-03-31	49.984 mi
Registration #11	2018-03-29	55.201 mi
Registration #12	2019-03-29	55.201 mi
Registration #13	2019-03-29	55.201 mi
Registration #14	2019-03-29	55.201 mi
Registration #15	2019-03-29	55.201 mi
Registration #16	2019-03-29	55.201 mi
Registration #17	2019-03-29	55.201 mi
Registration #18	2019-03-29	55.201 mi
Registration #19	2019-03-29	55.201 mi
Registration #20	2019-03-29	55.201 mi
Registration #21	2019-03-29	55.201 mi
Registration #22	2019-03-29	55.201 mi

More info >





Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	1013 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1030869