



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Blue
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 3

Date	2023-06-17
Pictures	12
Listing price	View report



source: cargurus.co.uk


Entry 2

Date	2023-06-14
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	37
Total items failed	3

MOT #14	2024-01-31 16:45
MOT test number	849861825359
Result	✓ Passed
Next expiry date	2025-01-30

MOT #13	2023-06-08 15:12
MOT test number	117728036193
Result	✓ Passed

MOT #12	2023-06-06 11:05
MOT test number	978557362619
Result	✗ Failed
<div><div>Advice</div> Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))</div> <div><div>Fail</div> Offside Front Brake pipe excessively corroded (1.1.11 (c))</div> <div><div>Advice</div> Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))</div> <div><div>Advice</div> Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))</div>	

**MOT #11**

2023-02-06 09:48

MOT test number

374710699039

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Coil spring corroded both front (5.3.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2023-02-06 09:48

MOT test number

452108108630

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Coil spring corroded both front (5.3.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9

2022-02-12 09:42

MOT test number

612123433159

Result**✓ Passed**

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Coil spring corroded all 4 springs (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8

2021-02-11 10:43

MOT test number

939051843280

Result**✓ Passed**

**MOT #7** 2020-08-10 12:10**MOT test number** 360808902507**Result** ✓ Passed**MOT #6** 2020-06-05 09:53**MOT test number** 489327072141**Result** ✓ Passed**MOT #5** 2019-04-25 09:08**MOT test number** 895169471569**Result** ✓ Passed**MOT #4** 2018-04-30 13:08**MOT test number** 470580531777**Result** ✓ Passed**Advice** Wheel trims fitted obscuring some components**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front tyre has cut in but not deep enough to reach cords**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2018-04-30 10:27**MOT test number** 611724750854**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front tyre has cut in but not deep enough to reach cords**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Wheel trims fitted obscuring some components



MOT #2	2017-05-10 10:45
MOT test number	754615009519
Result	✓ Passed
<div>Advice</div> Items removed from driver's view prior to test	

MOT #1	2016-04-05 12:37
MOT test number	994709215244
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-03-25
Last registration	2024-01-31
Complete history	See info



Registration #1	2013-03-25	22 mi
Registration #2	2016-04-05	19.420 mi
Registration #3	2017-05-10	23.718 mi
Registration #4	2018-04-30	27.372 mi
Registration #5	2018-04-30	27.373 mi
Registration #6	2019-04-25	30.933 mi
Registration #7	2020-06-05	34.421 mi
Registration #8	2020-08-10	34.952 mi
Registration #9	2020-08-10	34.952 mi
Registration #10	2020-08-10	34.952 mi
Registration #11	2020-08-10	34.952 mi
Registration #12	2020-08-10	34.952 mi
Registration #13	2020-08-10	34.952 mi
Registration #14	2020-08-10	34.952 mi
Registration #15	2020-08-10	34.952 mi
Registration #16	2020-08-10	34.952 mi
Registration #17	2020-08-10	34.952 mi
Registration #18	2020-08-10	34.952 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153