



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	Silver
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-07
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-25
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	26
Total items failed	2

MOT #11	2023-06-20 15:51
MOT test number	698720087719
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking & perished (5.2.3 (d) (ii))
Advice	Central Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material before & after flexi hose (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm cracking & perished (5.2.3 (e))
Advice	Offside Front Inner Brake pad(s) wearing thin 2-3mm (1.1.13 (a) (ii))

**MOT #10**

2023-06-20 10:19

MOT test number

402135096927

Result**✗ Failed**

- Advice** Central Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))
- MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2.8mm cracking & perished (5.2.3 (e))
- MAJOR** Offside Rear Brake pipe excessively corroded before & after flexi hose (1.1.11 (c))
- Advice** Offside Front Inner Brake pad(s) wearing thin 2-3mm (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking & perished (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material before & after flexi hose (1.1.11 (c))

MOT #9

2022-06-21 14:39

MOT test number

396986422515

Result**✓ Passed**

- Advice** Rear Tyre slightly damaged/cracking or perishing both sides rear tyres (5.2.3 (d) (ii))

MOT #8

2021-06-07 13:46

MOT test number

375998364882

Result**✓ Passed**

**MOT #7** 2021-06-07 13:46**MOT test number** 506310749779**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #6** 2020-06-26 16:10**MOT test number** 757920741048**Result** ✓ Passed**Advice** Nearside Front wiper split**MOT #5** 2020-06-25 10:42**MOT test number** 459748651511**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Front wiper split**MOT #4** 2019-04-08 13:58**MOT test number** 835817976301**Result** ✓ Passed



MOT #3	2019-04-08 10:47
MOT test number	947188791691
Result	✗ Failed
<div><div>MAJOR</div>Offside Front Position lamp not working (4.2.1 (a))</div> <div><div>MAJOR</div>Nearside Front Position lamp not working (4.2.1 (a))</div> <div><div>DANGEROUS</div>Offside Front Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))</div> <div><div>MAJOR</div>Windscreen washer not working (3.5 (a))</div>	
MOT #2	2017-10-21 10:51
MOT test number	254011149119
Result	✓ Passed
MOT #1	2016-10-29 09:44
MOT test number	922979825018
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	LV63EHG
Plate since	2019-03-29
Current registration	LV63EHG
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-31
Last registration	2023-06-20
Complete history	See info



Registration #1	2013-10-31	17 mi
Registration #2	2016-10-29	17.378 mi
Registration #3	2017-10-21	23.797 mi
Registration #4	2019-04-08	32.057 mi
Registration #5	2019-04-08	32.057 mi
Registration #6	2020-06-25	37.785 mi
Registration #7	2020-06-26	37.785 mi
Registration #8	2020-06-26	37.785 mi
Registration #9	2020-06-26	37.785 mi
Registration #10	2020-06-26	37.785 mi
Registration #11	2020-06-26	37.785 mi
Registration #12	2020-06-26	37.785 mi
Registration #13	2020-06-26	37.785 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4LACM940592
---------------	--------------