





report date: 2024-03-28

### General information

| Make                | PEUGEOT        |
|---------------------|----------------|
| Model               | 206 S          |
| Colour              | Silver         |
| Year of manufacture | 2004           |
| Top speed           | 107 mph        |
| 0 - 60 mph          | 12.2 seconds   |
| Gearbox             | 5 speed Manual |

### Engine & fuel consumption

| Power                   | 75 BHP              |
|-------------------------|---------------------|
| Max. torque             | 120 Nm at 2.800 rpm |
| Engine capacity         | 1.360 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 33.6 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 45.6 mpg            |
| CO2 emission            | 149 g/km            |
| CO2 label               | F                   |



CarCheck.co.uk page 1/15



report date: 2024-03-28

### Internet history

| г. |    |    | - 1 |  |
|----|----|----|-----|--|
| -1 | nт | rv | , , |  |
|    |    |    |     |  |

| LIICI Y I     |             |
|---------------|-------------|
| Date          | 2021-06-16  |
| Pictures      | 0           |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

| MOT history | M | OT | history |
|-------------|---|----|---------|
|-------------|---|----|---------|

| MOT expiry date    | 2024-06-28 |
|--------------------|------------|
| MOT pass rate      | 71 %       |
| MOT passed         | 17         |
| Failed MOT tests   | 7          |
| Total advice items | 24         |
| Total items failed | 17         |

| MOT #24          | 2023-06-21 13:11 |
|------------------|------------------|
| MOT test number  | 659799743151     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-06-28       |

| MOT #23  |  | 2022-06-29 13:41 |
|----------|--|------------------|
| MOT test | number   | 669652783176     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))  | )                |
| Advice   | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) | )                |
| Advice   | Offside Rear Service brake binding but not excessively (1.2.1 (f))                   |                  |

| MOT #22         | 2021-06-14 13:07 |
|-----------------|------------------|
| MOT test number | 968884742518     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/15



report date: 2024-03-28

**MOT #21** 2020-07-09 09:52

**MOT test number** 675100446908

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2019-07-10 09:20

MOT test number 892089013671

**Result** 
✓ Passed

**Advice** Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced bulk head becoming corroded (6.1.1 (c) (i))

Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #19** 2018-07-17 14:42

**MOT test number** 985722401963

CarCheck.co.uk page 4/15



**MOT #16** 

Fail

EG04YUU

report date: 2024-03-28

2016-07-01 10:32

**MOT #18** 2018-07-17 10:58 842226959065 **MOT** test number Result × Failed Fail Rear Exhaust system insecure (6.1.2 (a)) Minor Offside Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a)) Fail Emissions not tested (8.2.1.2 (d)) Rear Exhaust has a major leak of exhaust gases (6.1.2 (a)) Fail Offside Front Position lamp not working (4.2.1 (a)) Fail

 MOT #17
 2017-07-20 11:14

 MOT test number
 487026140790

 Result
 ✓ Passed

MOT test number 469856244666

Result Passed

 MOT #15
 2016-06-29 12:06

 MOT test number
 781222334509

 Result
 ★ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Offside Rear Registration plate lamp not working (1.1.C.1d)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 5/15



Result

EG04YUU

report date: 2024-03-28

**MOT #14** 2015-07-09 09:32

577510395198 **MOT** test number

Result ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #13** 2015-07-09 09:32

**MOT** test number 149710895176

**X** Failed

**Pass with rectification** Nearside Front Headlamp aim too low (1.8)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Front Headlamp aim too low (1.8)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2014-07-18 14:34

**MOT** test number 229469894179

Result ✓ Passed

**MOT #11** 2013-07-03 14:46

**MOT** test number 228174683410

Result Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



MOT #6

EG04YUU

report date: 2024-03-28

2010-07-19 12:17

MOT test number

Result

Rear Exhaust system not adequately supported (7.1.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

| MOT #9  | 2012-07-16 08:45 |
|---|------------------|
| MOT test number                                 | 515048692101     |
| Result  | <b>✓</b> Passed  |
| Notice Rear exhaust deteriated                  |                  |
| Advice Front Brake pad(s) wearing thin (3.5.1g) |                  |

| MOT #8          | 2011-07-13 14:46 |
|-----------------|------------------|
| MOT test number | 497414191112     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #7          | 2010-07-23 09:09 |
| MOT test number | 614584900283     |
| Result          | <b>✓</b> Passed  |

| MOT test number                                  | 544350900262    |
|--|-----------------|
| Result   | <b>X</b> Failed |
| Fail Front brake application uneven (3.7.B.2)    |                 |
| Fail Brakes imbalanced across an axle (3.7.B.5b) |                 |
| Fail Front brakes release unevenly (3.7.B.4)     |                 |

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #5 2009-07-24 11:56

**MOT test number** 924595709231

**Result** ✓ Passed

MOT #4 2009-07-24 11:56

MOT test number 494005809287

**Result** X Failed

**Pass with rectification** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

MOT #3 2008-07-18 10:29

**MOT test number** 470660208218

**Result** ✓ Passed

MOT #2 2007-07-19 11:22

**MOT test number** 914820707273

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2007-07-19 11:22

MOT test number 672740107259

**Result** X Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 8/15



report date: 2024-03-28

### Tax & MOT check



| Tax status       | Valid until 1 June |
|------------------|--------------------|
| Days left        | 33                 |
| MOT expiry date  | 28 June 2024       |
| Full MOT history | See MOT history    |

### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 9/15



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

### Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.   |             |
|--|-------------|
|  |             |
| THE STATE OF THE S |             |
|  |             |
| ***************************************  |             |
| ********   |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this PEUGEOT had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   | AK UK       |
| Plate since  |             |
| Current registration   | NK AIN      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 12/15



report date: 2024-03-28

### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >


CarCheck.co.uk page 13/15



EGO4YUU report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 23         |
| First mileage registration | 2004-07-22 |
| Last registration          | 2023-06-21 |
| Complete history           | See info   |



| Registration #1  | 2004-07-22 | 28 mi     |
|------------------|------------|-----------|
| Registration #2  | 2007-07-19 | 16.741 mi |
| Registration #3  | 2008-07-18 | 23.209 mi |
| Registration #4  | 2009-07-24 | 29.193 mi |
| Registration #5  | 2010-07-19 | 34.764 mi |
| Registration #6  | 2010-07-23 | 34.764 mi |
| Registration #7  | 2011-07-13 | 40.250 mi |
| Registration #8  | 2012-07-16 | 46.821 mi |
| Registration #9  | 2013-07-03 | 51.480 mi |
| Registration #10 | 2013-07-03 | 51.480 mi |
| Registration #11 | 2014-07-18 | 57.875 mi |
| Registration #12 | 2015-07-09 | 63.558 mi |
| Registration #13 |            | 71.777 es |
| Registration #14 |            | 71.777 es |
| Registration #15 |            | 71.777 es |
| Registration #16 |            | 71.777 es |
| Registration #17 |            | 11.777 es |
| Registration #18 |            | 71.777 es |
| Registration #19 |            | 71.777 es |
| Registration #20 |            | 71.777 es |
| Registration #21 |            | 11.777 es |
| Registration #22 |            | 11.777 es |
|                  |            |           |

More info >

CarCheck.co.uk page 14/15



EGO4YUU report date: 2024-03-28

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 |                 |
| S0482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

# Safety ratings

| NCAP rating | ***             |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1652 mm |
|---------------------|---------|
| Height              | 1433 mm |
| Length              | 3822 mm |
| Wheel base          | 2445 mm |
| Kerb weight         | 1025 kg |
| Max. allowed weight | 1450 kg |

# Additional information

| Fuel tank capacity                | 50 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 15/15          |

**Engine number** 

FSR94900767