



RF15NWW


report date: 2024-03-28

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	White
Year of manufacture	2015
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	94 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	43.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	126 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-05
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #6	2023-10-03 08:17
MOT test number	669657599202
Result	✓ Passed
Next expiry date	2024-10-05
Minor	Front Suspension arm ball joint dust cover severely deteriorated Both perishing (5.3.4 (b) (i))
Advice	Rear Direction indicator slightly discoloured Both (4.4.3 (a))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #5	2022-10-05 08:04
MOT test number	666572369093
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 185/55R16 (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4	2021-10-06 13:29
MOT test number	118948975004
Result	✓ Passed

**MOT #3** 2020-12-29 10:16**MOT test number** 296688613676**Result** ✓ Passed**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Non obligatory mirror damaged**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
lower arm rear bush perished (5.3.4 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
lower arm rear bush perished (5.3.4 (a) (i))**MOT #2** 2019-06-11 12:13**MOT test number** 957614240619**Result** ✓ Passed**MOT #1** 2018-06-05 11:49**MOT test number** 140246681060**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Covers and shields fitted



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
5 October 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	RF15NWW
Plate since	2015-05-29
Current registration	RF15NWW
Plate since	2015-05-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-06-30
Last registration	2023-10-03
Complete history	See info



Registration #1	2015-06-30	15 mi
Registration #2	2018-06-05	26.935 mi
Registration #3	2019-06-11	36.493 mi
Registration #4	2020-12-29	48.864 mi
Registration #5	2022-05-20	55.277 mi
Registration #6	2022-05-20	55.277 mi
Registration #7	2022-05-20	55.277 mi
Registration #8	2023-10-03	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1535 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1135 kg
Max. allowed weight	1560 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	K12B-1937936