



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	INSIGHT IMA SE
Colour	Blue
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	12.4 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	121 Nm at 4.500 rpm
Engine capacity	1.339 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	61.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





Internet history

Entry 1	
Date	2021-07-28
Pictures	3
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	28
Total items failed	7

MOT #22 2024-03-19 11:59

MOT test number 475867478899

Result ✓ Passed

Next expiry date 2025-03-24

Advice Brake pedal wearing smooth (1.1.2 (c))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #21 2024-03-19 11:36

MOT test number 936534246293

Result ✗ Failed

Advice Brake pedal wearing smooth (1.1.2 (c))

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20 2023-03-24 16:51

MOT test number 437615459961

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19** 2023-03-15 15:15**MOT test number** 451252408254**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #18** 2022-03-15 16:13**MOT test number** 394486128571**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #17** 2022-03-14 16:48**MOT test number** 327934267061**Result** ✗ Failed**Fail** Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2021-03-20 13:55**MOT test number** 203040651030**Result** ✓ Passed

**MOT #15** 2020-03-25 14:34**MOT test number** 655742255359**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2019-02-12 15:50**MOT test number** 574269985353**Result** ✓ Passed**MOT #13** 2018-07-17 10:55**MOT test number** 216751945426**Result** ✓ Passed**MOT #12** 2018-01-24 12:58**MOT test number** 780581868575**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #11** 2017-07-29 13:18**MOT test number** 397928105862**Result** ✓ Passed**MOT #10** 2017-07-04 09:13**MOT test number** 404957151431**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

**MOT #9** 2017-01-04 13:39**MOT test number** 112429642102**Result** ✓ Passed**MOT #8** 2016-07-08 10:12**MOT test number** 153484589045**Result** ✓ Passed**MOT #7** 2016-06-18 10:15**MOT test number** 759798796100**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2015-12-21 09:33**MOT test number** 815756079150**Result** ✓ Passed**MOT #5** 2015-06-25 09:41**MOT test number** 586556375163**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-06-23 13:53**MOT test number** 257414375464**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)



MOT #3	2014-06-28 11:01
MOT test number	177729974117
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Items removed from driver's view prior to test

MOT #2	2014-06-26 12:34
MOT test number	599227574121
Result	✗ Failed
Notice	Child seat fitted not allowing full inspection of adult belt
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Notice	Items removed from driver's view prior to test

MOT #1	2013-06-25 11:19
MOT test number	908046173123
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2010-08-11
Last registration	2024-03-19
Complete history	See info



Registration #1	2010-08-11	16 mi
Registration #2	2013-06-25	21.514 mi
Registration #3	2014-06-26	27.790 mi
Registration #4	2014-06-28	27.873 mi
Registration #5	2015-06-23	38.338 mi
Registration #6	2015-06-25	38.446 mi
Registration #7	2015-12-21	54.355 mi
Registration #8	2016-06-18	69.381 mi
Registration #9	2016-07-08	71.902 mi
Registration #10	2017-01-04	85.462 mi
Registration #11	2017-07-04	98.117 mi
Registration #12	2017-07-29	98.453 mi
Registration #13	2018-01-01	100.000 mi
Registration #14	2018-01-01	100.000 mi
Registration #15	2018-01-01	100.000 mi
Registration #16	2018-01-01	100.000 mi
Registration #17	2018-01-01	100.000 mi
Registration #18	2018-01-01	100.000 mi
Registration #19	2018-01-01	100.000 mi
Registration #20	2018-01-01	100.000 mi
Registration #21	2018-01-01	100.000 mi
Registration #22	2018-01-01	100.000 mi
Registration #23	2018-01-01	100.000 mi
Registration #24	2018-01-01	100.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1425 mm
Length	4396 mm
Wheel base	2550 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 1028716