



YR03KTZ

report date: 2024-03-29

General information

Make	NISSAN
Model	ELGRAND
Colour	White
Year of manufacture	2003
Gearbox	1 speed automatic

Engine & fuel consumption

Engine capacity	3.500 cc
Fuel type	Petrol




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-12
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-15
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	39
Total items failed	0

MOT #9	2023-08-11 09:26
MOT test number	863808204197
Result	✓ Passed
Next expiry date	2024-08-15
Advice	Front Registration plate insecure but not likely to fall off (0.1 (a))

**MOT #8**

2023-08-01 14:17

MOT test number

981786423134

Result**✗ Failed****DANGEROUS** Nearside Rear Anti-roll bar attachment bracket/mounting fractured (5.3.3 (b) (ii))**MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm Secondary rubber (5.2.3 (e))**MAJOR** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm Secondary rubber (5.2.3 (e))**MAJOR** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm Secondary rubber (5.2.3 (e))**MAJOR** Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #7**

2022-08-16 09:31

MOT test number

526950908547

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2022-08-02 16:27**MOT test number** 528016783082**Result** ✗ Failed**MAJOR** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**MAJOR** Nearside Front Inner Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #5** 2021-08-12 15:11**MOT test number** 923850305867**Result** ✓ Passed**Advice** Corrosion building up along the underside of the vehicle**Advice** Exhaust system corroded but still secure**MOT #4** 2021-08-06 15:21**MOT test number** 975778761245**Result** ✗ Failed**Advice** Corrosion building up along the underside of the vehicle**MAJOR** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))**Advice** Exhaust system corroded but still secure**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MOT #3** 2020-08-14 15:44**MOT test number** 622683215047**Result** ✓ Passed**Advice** 3rd row seats stowed away not allowing full inspection of adult belts**Minor** Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #2** 2020-08-13 10:14**MOT test number** 457739972120**Result** ✗ Failed

DANGEROUS Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

Minor Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Spare tyre defective

MAJOR Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice 3rd row seats stowed away not allowing full inspection of adult belts

DANGEROUS Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MAJOR Offside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))

DANGEROUS Nearside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #1 2019-04-02 11:03**MOT test number** 138154312770**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 August 2024

Tax status	Valid until 1 September
------------	-------------------------

Days left	125
-----------	-----

MOT expiry date	15 August 2024
-----------------	----------------

Full MOT history	See MOT history
------------------	---------------------------------



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	YR03KTZ
Plate since	2019-03-29
Current registration	YR03KTZ
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2019-04-01
Last registration	2023-08-11
Complete history	See info



Registration #1	2019-04-01	7 mi
Registration #2	2019-04-02	34.489 mi
Registration #3	2020-08-13	42.625 mi
Registration #4	2020-08-14	42.628 mi
Registration #5	2021-08-06	44.293 mi
Registration #6	2021-08-12	71.272 mi
Registration #7	2023-08-11	71.272 mi
Registration #8	2023-08-11	71.272 mi
Registration #9	2023-08-11	71.272 mi
Registration #10	2023-08-11	71.272 mi
Registration #11	2023-08-11	71.272 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Number of seats	8
Engine number	NOT KNOWN