



LR60WJN

report date: 2024-03-28

General information

Make	FORD
Model	FIESTA EDGE
Colour	Black
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	114 Nm at 4.200 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-07
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	2

MOT #14	2023-08-04 10:28
MOT test number	567637900212
Result	✓ Passed
Next expiry date	2024-08-03
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-06-10 12:28
MOT test number	445557641616
Result	✓ Passed

MOT #12	2021-06-16 08:44
MOT test number	851432133392
Result	✓ Passed

MOT #11	2020-10-07 09:07
MOT test number	878195244901
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10** 2020-10-07 08:39**MOT test number** 249930582989**Result** ✗ Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
Inner side wall (5.2.3 (d) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2019-11-04 08:57**MOT test number** 490460633287**Result** ✓ Passed**MOT #8** 2018-09-28 08:46**MOT test number** 930144824322**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #7 2018-09-28 08:46**MOT test number** 133699614518**Result** ✗ Failed

Advice Offside Rear Nail in tyre

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #6 2017-08-15 11:02**MOT test number** 966210803324**Result** ✓ Passed

**MOT #5** 2016-08-11 14:26**MOT test number** 706351923464**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-08-11 09:25**MOT test number** 419317862043**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2015-09-26 08:38**MOT test number** 650139848293**Result** ✓ Passed**MOT #2** 2014-09-19 13:17**MOT test number** 207272064204**Result** ✓ Passed**MOT #1** 2013-09-13 12:09**MOT test number** 706626253205**Result** ✓ Passed**Notice** O/s/f tyre wall bad cuts but no cord exposed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	LR60WJN
Plate since	2019-03-28
Current registration	LR60WJN
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2023-08-04
Complete history	See info



Registration #1	2010-09-30	28 mi
Registration #2	2013-09-13	15.437 mi
Registration #3	2014-09-19	19.295 mi
Registration #4	2015-09-26	23.567 mi
Registration #5	2016-08-11	26.803 mi
Registration #6	2016-08-11	26.803 mi
Registration #7	2017-08-15	31.913 mi
Registration #8	2018-09-28	36.001 mi
Registration #9	2019-09-28	36.001 mi
Registration #10	2019-09-28	36.001 mi
Registration #11	2019-09-28	36.001 mi
Registration #12	2019-09-28	36.001 mi
Registration #13	2019-09-28	36.001 mi
Registration #14	2019-09-28	36.001 mi
Registration #15	2019-09-28	36.001 mi
Registration #16	2019-09-28	36.001 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	AU64848