



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B







Internet history

Entry 1

Date	2022-01-12
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-23
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	29
Total items failed	11

MOT #18 2024-01-19 11:33**MOT test number** 718579342376**Result** Passed**Next expiry date** 2025-01-23

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Rear Lower Coil spring corroded (5.3.1 (b) (i))
- Advice** Central Front Oil leak, but not excessive upper lower engine bay area around turbo slightly (8.4.1 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))
- Advice** Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))

MOT #17 2023-01-24 15:53**MOT test number** 455340581911**Result** Passed**MOT #16** 2023-01-16 14:47**MOT test number** 975130566781**Result** Failed

- Fail** Offside Rear Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))

**MOT #15**

2022-01-24 17:22

MOT test number

663759558587

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2021-01-09 13:04

MOT test number

678573343259

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Offside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #13**

2021-01-09 11:06

MOT test number

499120955606

Result

✗ Failed

Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin Both sides (1.1.13 (a) (ii))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Fail** Nearside Rear Anti-roll bar fractured (5.3.3 (b) (ii))**Advice** Offside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2020-01-11 10:44**MOT test number** 238590920349**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage damaged but not seriously weakened (5.3.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Exhaust emits black smoke during acceleration (8.2.1.2 (g))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #11** 2019-01-02 16:49**MOT test number** 213463049017**Result** ✓ Passed**MOT #10** 2019-01-02 11:45**MOT test number** 566285986423**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2018-01-16 11:42**MOT test number** 893390501198**Result** ✓ Passed

**MOT #8** 2018-01-16 11:42**MOT test number** 929066531823**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2017-01-04 10:56**MOT test number** 869619110933**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit inside edge (4.1.E.1)**Advice** Nearside Front Inner Tyre worn close to the legal limit on inside edge (4.1.E.1)**MOT #6** 2016-01-14 16:26**MOT test number** 557184088529**Result** ✓ Passed**MOT #5** 2016-01-14 14:53**MOT test number** 219476846669**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm inner edge (4.1.E.1)**MOT #4** 2015-01-15 12:22**MOT test number** 469315615091**Result** ✓ Passed**Notice** Both rear tyres becoming worn on inside edges



MOT #3	2013-12-04 15:54
MOT test number	829148933388
Result	✓ Passed
MOT #2	2013-04-04 15:12
MOT test number	889164193092
Result	✓ Passed
MOT #1	2013-03-27 09:37
MOT test number	115546683450
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
23 January 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	23 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	FY10VXR
Plate since	2019-09-29
Current registration	FY10VXR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-03-25
Last registration	2024-01-19
Complete history	See info



Registration #1	2010-03-25	17 mi
Registration #2	2013-03-27	54.364 mi
Registration #3	2013-04-04	54.651 mi
Registration #4	2013-12-04	59.145 mi
Registration #5	2015-01-15	76.800 mi
Registration #6	2016-01-14	92.917 mi
Registration #7	2016-01-14	92.917 mi
Registration #8	2017-01-04	112.940 mi
Registration #9	2018-01-16	137.315 mi
Registration #10	2018-01-16	137.315 mi
Registration #11	2019-01-01	151.317 mi
Registration #12	2019-01-01	151.317 mi
Registration #13	2019-01-01	151.317 mi
Registration #14	2019-01-01	151.317 mi
Registration #15	2019-01-01	151.317 mi
Registration #16	2019-01-01	151.317 mi
Registration #17	2019-01-01	151.317 mi
Registration #18	2019-01-01	151.317 mi
Registration #19	2019-01-01	151.317 mi
Registration #20	2019-01-01	151.317 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602