



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 D5 SE S40
Colour	Red
Year of manufacture	2007
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	178 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-08-14
Pictures	39
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-03-29
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	4

MOT #16	2021-03-30 12:30
MOT test number	202398383761
Result	✓ Passed
Next expiry date	2022-03-29
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (ii))

MOT #15	2020-03-12 11:05
MOT test number	505195721614
Result	✓ Passed
Advice	Nearside Front Tyre worn on edges

MOT #14	2020-03-11 12:42
MOT test number	260399497380
Result	✗ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Lipped (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn on edges

**MOT #13** 2019-03-05 12:49**MOT test number** 886299704003**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #12** 2018-03-19 10:05**MOT test number** 916116086811**Result** ✓ Passed**MOT #11** 2018-03-19 10:05**MOT test number** 867635210273**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #10** 2016-04-21 10:05**MOT test number** 159704360913**Result** ✓ Passed**MOT #9** 2015-03-30 10:41**MOT test number** 788949485086**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2015-03-30 10:41**MOT test number** 138929485070**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2014-04-01 09:04**MOT test number** 406151994014**Result** ✓ Passed**MOT #6** 2014-03-24 13:05**MOT test number** 327623384033**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-03-21 16:18**MOT test number** 478540783055**Result** ✓ Passed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2013-03-21 16:18**MOT test number** 178960783058**Result** ✗ Failed**Advice** Rear Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)



<b>MOT #3</b>	2012-03-15 12:54
---------------	------------------

<b>MOT test number</b>	946545672024
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
---------------	---

<b>Advice</b>	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
---------------	--

<b>MOT #2</b>	2011-03-14 15:17
---------------	------------------

<b>MOT test number</b>	845513071035
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-03-29 12:13
---------------	------------------

<b>MOT test number</b>	522318480010
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✕  
Untaxed

Tax expired:  
10 March 2022

✕  
MOT

Expired:  
29 March 2022

Tax status	Expired at 10 March 2022
Days left	782 days too late
MOT expiry date	29 March 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-29
Last registration	2021-03-30
Complete history	<a href="#">See info</a>



Registration #1	2007-03-29	23 mi
Registration #2	2010-03-29	28.188 mi
Registration #3	2011-03-14	34.314 mi
Registration #4	2012-03-15	37.271 mi
Registration #5	2013-03-21	44.990 mi
Registration #6	2014-03-24	57.723 mi
Registration #7	2014-04-01	57.723 mi
Registration #8	2015-03-30	23.359 mi
Registration #9	2015-03-30	73.359 mi
Registration #10	2015-03-30	73.359 mi
Registration #11	2015-03-30	73.359 mi
Registration #12	2015-03-30	73.359 mi
Registration #13	2015-03-30	73.359 mi
Registration #14	2015-03-30	73.359 mi
Registration #15	2015-03-30	73.359 mi
Registration #16	2015-03-30	73.359 mi
Registration #17	2015-03-30	73.359 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1543 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	516960
---------------	--------