



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	White
Year of manufacture	2010
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-05-30
Pictures	5
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	33
Total items failed	11

MOT #15	2023-05-19 13:16
MOT test number	945990385211
Result	✓ Passed
Next expiry date	2024-05-19
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #14**

2023-05-19 09:21

MOT test number

133230070706

Result**✗ Failed****Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13**

2022-05-19 14:16

MOT test number

625570565328

Result**✓ Passed****MOT #12**

2021-05-20 08:42

MOT test number

305725607698

Result**✓ Passed****Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both rear inner sills (6.1.1 (c) (i))

**MOT #11**

2021-05-18 15:16

MOT test number

750479833127

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both rear inner sills (6.1.1 (c) (i))

MOT #10

2020-11-09 13:43

MOT test number

995630787330

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point / sill area (6.1.1 (c) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point / sill area (6.1.1 (c) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #9** 2020-11-02 18:44**MOT test number** 155696637567**Result** ✗ Failed**Fail** Offside Rear Suspension arm damaged and seriously weakened trailing arm weakened by corrosion (5.3.3 (b) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point / sill area (6.1.1 (c) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Suspension arm corroded and seriously weakened trailing arm (5.3.3 (b) (i))**Fail** Brake pipe excessively corroded both front to rear (1.1.11 (c))**Advice** Nearside Rear Inner Vehicle structure is corroded but structural rigidity is not significantly reduced jacking point / sill area (6.1.1 (c) (i))**Fail** Horn sound not in accordance with requirements (7.7 (c))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #8** 2020-03-12 16:05**MOT test number** 770848455244**Result** ✓ Passed**MOT #7** 2019-03-13 15:10**MOT test number** 845051484588**Result** ✓ Passed**MOT #6** 2018-03-13 10:29**MOT test number** 625821858559**Result** ✓ Passed



MOT #5	2017-03-13 10:47
MOT test number	150216044911
Result	✓ Passed
MOT #4	2016-03-10 12:29
MOT test number	283256772905
Result	✓ Passed
MOT #3	2015-03-12 11:55
MOT test number	859831375087
Result	✓ Passed
MOT #2	2014-03-12 11:28
MOT test number	555191374080
Result	✓ Passed
MOT #1	2013-03-13 10:28
MOT test number	556702173082
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 December
Days left	215
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-27
Last registration	2023-05-19
Complete history	See info



Registration #1	2010-09-27	7 mi
Registration #2	2013-03-13	26.771 mi
Registration #3	2014-03-12	33.242 mi
Registration #4	2015-03-12	40.759 mi
Registration #5	2016-03-10	46.646 mi
Registration #6	2017-03-13	52.408 mi
Registration #7	2018-03-13	57.393 mi
Registration #8	2019-03-13	62.677 mi
Registration #9	2020-03-12	67.984 mi
Registration #10	2021-03-12	73.291 mi
Registration #11	2022-03-12	78.598 mi
Registration #12	2023-03-12	83.905 mi
Registration #13	2024-03-12	89.212 mi
Registration #14	2025-03-12	94.519 mi
Registration #15	2026-03-12	99.826 mi
Registration #16	2027-03-12	105.133 mi
Registration #17	2028-03-12	110.440 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	112085