



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 DSPORT PLUS
Colour	Silver
Year of manufacture	2013
Top speed	132 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-27
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	15
Total items failed	15

MOT #13	2023-06-28 10:50
MOT test number	268041788309
Result	✓ Passed
Next expiry date	2024-06-27

MOT #12	2023-06-27 09:58
MOT test number	689088386824
Result	✗ Failed
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	

MOT #11	2022-11-11 16:02
MOT test number	209682745030
Result	✓ Passed

MOT #10	2021-11-05 14:45
MOT test number	426432977347
Result	✓ Passed

**MOT #9** 2021-11-04 16:55**MOT test number** 391888644588**Result** ✗ Failed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #8** 2020-09-24 09:37**MOT test number** 495122765823**Result** ✓ Passed**MOT #7** 2020-09-23 09:47**MOT test number** 303266903604**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #6** 2020-07-09 07:57**MOT test number** 153282546675**Result** ✓ Passed**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**Advice** Tyre has a cut but not deep enough to reach the ply or cords both front outer (5.2.3 (d) (i))**MOT #5** 2019-04-11 10:03**MOT test number** 222187558934**Result** ✓ Passed

**MOT #4** 2018-01-23 16:55**MOT test number** 285000472105**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2018-01-23 11:46**MOT test number** 196377696024**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Central Rear Exhaust system not adequately supported (7.1.1)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Front Exhaust system not adequately supported (7.1.1)**Fail** Brake disc in such a condition that it is seriously weakened all (3.5.1i)**MOT #2** 2017-01-04 13:46**MOT test number** 393625598639**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust bracket broken off



MOT #1

2017-01-03 12:50

MOT test number

775905026672

Result		✗ Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice	Anti freeze below minimum	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice	Exhaust bracket broken off	
Advice	Brake pad(s) wearing thin (3.5.1g)	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice	Brake fluid low	
Fail	Offside Rear coil spring broken (2.4.C.1a)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



Tax & MOT check

X

Untaxed

Tax expired:
3 May 2023

✓

MOT

Expires:
27 June 2024

Tax status	Expired at 3 May 2023
Days left	362 days too late
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-11-11
Last registration	2023-06-28
Complete history	See info



Registration #1	2013-11-11	12 mi
Registration #2	2017-01-03	42.170 mi
Registration #3	2017-01-04	42.171 mi
Registration #4	2018-01-23	42.997 mi
Registration #5	2018-01-23	43.005 mi
Registration #6	2019-04-11	48.733 mi
Registration #7	2020-07-09	56.277 mi
Registration #8	2020-09-23	56.322 mi
Registration #9	2020-09-23	56.322 mi
Registration #10	2020-09-23	56.322 mi
Registration #11	2020-09-23	56.322 mi
Registration #12	2020-09-23	56.322 mi
Registration #13	2020-09-23	56.322 mi
Registration #14	2020-09-23	56.322 mi
Registration #15	2020-09-23	56.322 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1619 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FJBS1764643