



report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D5 SE LUX NAV AWD
Colour	Red
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	440 Nm at 3.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 3


Date	2022-12-15
Pictures	6
Listing price	View report



source: autotrader.co.uk

Entry 2




Date	2021-06-16
Pictures	16
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-31
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	12
Total items failed	1

MOT #7	2024-01-29 13:13
MOT test number	192633209010
Result	✓ Passed
Next expiry date	2025-01-31
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #6	2024-01-25 15:17
MOT test number	234077978153
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Nearside Front Headlamp insecure (4.1.1 (c))
MAJOR	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
MAJOR	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #5** 2023-01-20 13:59**MOT test number** 877533881970**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #4** 2022-02-01 16:27**MOT test number** 760861207395**Result** ✓ Passed**MOT #3** 2022-02-01 12:31**MOT test number** 320950666681**Result** ✗ Failed**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #2** 2020-06-08 11:11**MOT test number** 613730235273**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on limit of 1.6mm (5.2.3 (e))**MOT #1** 2019-03-22 16:21**MOT test number** 691068555636**Result** ✓ Passed**Advice** Windscreen washers barely hit screen



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 January
Days left	247
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-16
Last registration	2024-01-29
Complete history	See info



Registration #1	2016-03-16	19 mi
Registration #2	2019-03-22	45.288 mi
Registration #3	2020-06-08	58.921 mi
Registration #4	2020-06-08	58.921 mi
Registration #5	2020-06-08	58.921 mi
Registration #6	2022-02-01	64.533 mi
Registration #7	2022-02-01	64.533 mi
Registration #8	2022-02-01	64.533 mi
Registration #9	2022-02-01	64.533 mi
Registration #10	2022-02-01	64.533 mi
Registration #11	2022-02-01	64.533 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1865 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

1635675