




report date: 2024-03-29

General information

Make	VOLVO
Model	XC70 XC70 D5 AWD SE EU4
Colour	Green
Year of manufacture	2006
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-12
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2025-03-18
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	49
Total items failed	10

MOT #27	2024-03-19 16:03
MOT test number	526726801591
Result	✓ Passed
Next expiry date	2025-03-18
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #26	2024-03-19 09:58
MOT test number	549785008792
Result	✗ Failed
MAJOR	Nearside Parking brake inoperative on one side (1.4.1 (a))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
DANGEROUS	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))

MOT #25	2023-03-02 13:44
MOT test number	658375697879
Result	✓ Passed
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #24** 2023-03-02 13:44**MOT test number** 633559891991**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #23** 2022-03-16 14:10**MOT test number** 125508240276**Result** ✓ Passed**MOT #22** 2022-03-14 16:24**MOT test number** 950993602779**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))**MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #21** 2021-02-25 17:08**MOT test number** 716468380894**Result** ✓ Passed**MOT #20** 2021-02-25 12:40**MOT test number** 443564577094**Result** ✗ Failed**MAJOR** Offside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))**MAJOR** Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))

**MOT #19**

2020-03-03 17:24

**MOT test number**

174197060649

**Result**

✓ Passed

**Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #18**

2020-02-24 12:51

**MOT test number**

793180860642

**Result**

✗ Failed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Offside Front Brake hose slightly twisted (1.1.12 (b) (i))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #17**

2019-02-21 10:25

**MOT test number**

955828853247

**Result**

✓ Passed

**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16** 2018-03-10 12:37**MOT test number** 969440325080**Result** ✓ Passed**MOT #15** 2017-07-21 17:42**MOT test number** 708707050811**Result** ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Non obligatory mirror damaged
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #14** 2017-07-21 14:12**MOT test number** 273554117472**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Non obligatory mirror damaged
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #13** 2017-07-17 10:27**MOT test number** 842820724348**Result** ✗ Failed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Exhaust system not adequately supported (7.1.1)**Advice** Nearside Front Tyre worn close to the legal limit worn on inside edge (4.1.E.1)**Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #12** 2016-07-29 16:42**MOT test number** 385539544095**Result** ✓ Passed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #11** 2016-07-29 16:42**MOT test number** 423177706056**Result** ✗ Failed**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #10** 2016-07-20 09:47**MOT test number** 507083490493**Result** ✗ Failed**Fail** Headlamp levelling device obviously defective when set to night time use h/lamps lower then raise to correct height before dropping down off scale in 2 to 3 seconds (1.7.2)**Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #9** 2015-08-01 13:07**MOT test number** 886053715221**Result** ✓ Passed**MOT #8** 2015-07-24 11:32**MOT test number** 458155505231**Result** ✗ Failed**Fail** Offside Headlamp aim too low (1.8)**Fail** Nearside Headlamp aim too low (1.8)**MOT #7** 2014-07-21 10:49**MOT test number** 659142604210**Result** ✓ Passed**Notice** One of two brackets broken on exhaust under rear axle**Notice** Items removed from driver's view prior to test**Notice** Non obligatory mirror damaged**Advice** Suspension arm has slight play in a track control arm inner bush (2.5.B.2b)**MOT #6** 2013-07-29 11:31**MOT test number** 317070413417**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2012-07-05 16:16**MOT test number** 298487482167**Result** ✓ Passed



**MOT #4** 2011-06-13 14:35**MOT test number** 299054661178**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front discs are pitted**Notice** Rear brake discs are worn and pitted**MOT #3** 2010-06-21 10:00**MOT test number** 203092270483**Result** ✓ Passed**Notice** Rear brakes rusty.**MOT #2** 2009-07-16 11:11**MOT test number** 360687899101**Result** ✓ Passed**MOT #1** 2009-01-26 17:14**MOT test number** 192506129096**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
18 March 2025

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	18 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2006-01-31
Last registration	2024-03-19
Complete history	<a href="#">See info</a>



Registration #1	2006-01-31	13 mi
Registration #2	2009-01-26	30.050 mi
Registration #3	2009-07-16	34.158 mi
Registration #4	2010-06-21	40.305 mi
Registration #5	2011-06-13	55.800 mi
Registration #6	2012-07-05	66.753 mi
Registration #7	2013-07-29	71.478 mi
Registration #8	2014-07-21	76.134 mi
Registration #9	2015-07-24	83.260 mi
Registration #10	2015-08-01	83.415 mi
Registration #11	2016-07-20	90.076 mi
Registration #12	2016-07-29	90.290 mi
Registration #13	2016-07-29	90.290 mi
Registration #14	2017-07-17	100.557 mi
Registration #15	2017-07-21	100.942 mi
Registration #16	2019-05-29	101.277 mi
Registration #17	2019-05-29	101.277 mi
Registration #18	2019-05-29	101.277 mi
Registration #19	2019-05-29	101.277 mi
Registration #20	2019-05-29	101.277 mi
Registration #21	2019-05-29	101.277 mi
Registration #22	2019-05-29	101.277 mi
Registration #23	2019-05-29	101.277 mi
Registration #24	2019-05-29	101.277 mi
Registration #25	2019-05-29	101.277 mi
Registration #26	2019-05-29	101.277 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2100 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	363695