



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Black
Year of manufacture	2009
Top speed	104 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	112 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2020-08-30
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	38
Total items failed	3

MOT #13	2019-08-08 08:57
MOT test number	843387892549
Result	✓ Passed
Next expiry date	2020-08-30
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #12	2018-08-31 09:58
MOT test number	144417136476
Result	✓ Passed
Advice	Near side front bumper damaged
Advice	Off side front tyre slightly wearing on the inner edge

MOT #11	2017-06-26 11:55
MOT test number	429840842856
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10**

2016-07-13 08:18

MOT test number

704384308005

Result

✓ Passed

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides / rear bush A (2.4.G.2)

Advice Offside Front Seat belt stitching slightly frayed G (5.2.2b)

Advice Offside Rear Tyre worn close to the legal limit 2.5mm and perished 195/55 R15 V A (4.1.E.1)

MOT #9

2016-07-13 08:18

MOT test number

486849603622

Result

✗ Failed

Advice Offside Rear Tyre worn close to the legal limit 2.5mm and perished 195/55 R15 V A (4.1.E.1)

Pass with rectification Windscreen wiper does not clear the windscreen effectively both 21"/18" Aero (8.2.2)

Advice Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides / rear bush A (2.4.G.2)

Advice Offside Front Seat belt stitching slightly frayed G (5.2.2b)

MOT #8

2015-08-10 16:31

MOT test number

407519231521

Result

✓ Passed

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Front number plate damaged

Advice Front brake pads have roughly 5-6 thousand miles left

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

Advice Offside front and offside rear tyres perishing 195/55 R15 V R2009/F2013



MOT #7	2015-08-10 10:48
MOT test number	470809903127
Result	✗ Failed
Advice	Offside front and offside rear tyres perishing 195/55 R15 V R2009/F2013
Advice	Offside Front Seat belt stitching slightly frayed (5.2.2b)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
Fail	Parking brake lever has no reserve travel (3.1.6b)
Advice	Front number plate damaged
Advice	Front brake pads have roughly 5-6 thousand miles left
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)

MOT #6	2014-08-11 15:58
MOT test number	447463624257
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Items removed from driver's view prior to test
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	Both rear tyres perished/cracked

**MOT #5** 2014-08-11 10:38**MOT test number** 918433024279**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Items removed from driver's view prior to test**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Both rear tyres perished/cracked**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #4** 2013-08-08 14:53**MOT test number** 298020423277**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Nsf tyre outer sidewall perished**Notice** Front tyres on 3m**MOT #3** 2012-11-15 16:51**MOT test number** 896550522374**Result** ✓ Passed**MOT #2** 2012-08-14 09:12**MOT test number** 408087522291**Result** ✓ Passed



MOT #1	2012-06-25 14:29
MOT test number	315527972142
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-07-31
Last registration	2019-08-08
Complete history	See info



Registration #1	2009-07-31	22 mi
Registration #2	2012-06-25	9.777 mi
Registration #3	2012-08-14	10.336 mi
Registration #4	2012-11-15	10.382 mi
Registration #5	2013-08-08	19.329 mi
Registration #6	2014-08-11	32.639 mi
Registration #7	2014-08-11	32.639 mi
Registration #8	2019-08-08	32.639 mi
Registration #9	2019-08-08	32.639 mi
Registration #10	2019-08-08	32.639 mi
Registration #11	2019-08-08	32.639 mi
Registration #12	2019-08-08	32.639 mi
Registration #13	2019-08-08	32.639 mi
Registration #14	2019-08-08	32.639 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BZG258667