

Ford



General information

Make	FORD
Model	GALAXY TITANIUM TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.7 mpg
CO2 emission	189 g/km
CO2 label	J







Internet history

Entry	1

Date Pictures 2021-07-26

Listing price

View report

8









source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-10
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	21
Total items failed	5

MOT #14	2023-05-10 09:19
MOT test number	134095525125
Result	✓ Passed
Next expiry date	2024-05-10

MOT #13	2022-04-13 14:42
MOT test number	273992533247
Result	✓ Passed

MOT #12	2021-04-27 12:09
MOT test number	287753373373
Result	✓ Passed

MOT #	11	2021-04-26 13:19
MOT te	est number	623187705188
Result		🗙 Failed
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	





2019-04-04 16:25

MOT #10		2020-05-11 14:35
MOT test	number	449216362010
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9

мот	test	number	
-----	------	--------	--

MOT test number	378153845028
Result	🗸 Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4	4 (b) (i))
Advice Rear Brake hose has slight corrosion to ferrule Both sides (1.1.12 (f) (i))	
Advice Undertrays and covers fitted obstructing view of some components.	
Advice Offside Rear Valve stem slightly damaged (5.2.3 (j))	

MOT #8		2018-04-05 14:49
MOT test number		942511767088
Result		✓ Passed
Advice Rear regi	istration plate deteriorated but not likely to be misread (6.3.1d)	
Advice Front reg	gistration plate deteriorated but not likely to be misread (6.3.1d)	
Advice Offside R	Rear Nail in tyre	
Advice Nearside	Front fog light in/op	



NJ09 [°]	TEO
report date:	2024-03-28

MOT #7	2017-04-03 09:36
MOT test number	912303882257
Result	✓ Passed
Advice N/s/f fog light in/op	
Advice Offside Rear Nail in tyre	
MOT #6	2016-03-14 15:04
	045005620520

MOT test number	945095638539
Result	✓ Passed
Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #5		2015-03-30 10:44
MOT test	number	826759485082
Result		✓ Passed
Notice	Nearside front fog light inop	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #4		2015-03-30 10:44
MOT test number		578059485005
Result		🗙 Failed
Notice Nearside front for	og light inop	
Pass with rectification	Nearside Front Direction indicator not working (1.4.A.2c)	
Notice Child seat fitted	not allowing full inspection of adult belt	





2012-03-13 10:28

106343472479

✓ Passed

MOT #3	2014-03-14 10:15
MOT test number	776983674003
Result	✓ Passed
NoticeChild seat fitted not allowing full inspection of adult beltNoticeN/s/f fog light in/op	
MOT #2	2013-03-09 11:27
MOT test number	357198163029
Result	✓ Passed

MOT #1

Centre rear child seat fitted

MOT test number

Result

Notice



Tax & MOT check

► Tax 1 August 2024	/ ked	Expires: 10 May 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			10 May 2024
Full MOT history			See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-03-13
Last registration	2023-05-10
Complete history	See info



Registration #1	2009-03-13	7 mi
Registration #2	2012-03-13	29.722 mi
Registration #3	2013-03-09	35.614 mi
Registration #4	2014-03-14	43.453 mi
Registration #5	2015-03-30	52.142 mi
Registration #6	2016-03-14	59.535 mi
Registration #7	2017-04-03	66.843 mi
Registration #8	2018-04-05	71.362 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1943 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles	2
Engine number	9G39426