



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI (100BHP)
Colour	Blue
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN

**MOT history**

MOT #24	2019-10-14 09:18
MOT test number	191805885021
Result	✓ Passed
Next expiry date	2020-11-02
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23	2018-10-11 08:04
MOT test number	887118517156
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #22	2018-10-09 15:09
MOT test number	248294406890
Result	✗ Failed
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #21	2017-10-24 14:36
MOT test number	670159616290
Result	✓ Passed

**MOT #20**

2017-10-18 10:21

MOT test number

208372500160

Result**✗ Failed****Fail**

Offside rear brake binding (3.7.B.1)

Fail

Driver's door cannot be opened from outside the vehicle (6.2.B.1b)

Fail

Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

Fail

Offside Track rod end ball joint has excessive play (2.2.B.1f)

Fail

Nearside Windscreen wiper blade insecure (8.2.2)

Fail

Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #19

2016-10-31 12:45

MOT test number

843347642904

Result**✓ Passed****MOT #18**

2015-11-03 14:39

MOT test number

783292075229

Result**✓ Passed****Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #17**

2015-10-28 10:27

MOT test number

181418578083

Result**✗ Failed****Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #16**

2014-09-24 14:37

MOT test number

659357264209

Result**✓ Passed****Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #15**

2014-09-24 12:08

MOT test number

238947264245

Result**✗ Failed****Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #14	2013-10-18 09:14
MOT test number	906721593275
Result	✓ Passed
Notice	Exhaust slightly deteriorated

MOT #13	2013-01-26 11:29
MOT test number	169436823057
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Items removed from driver's view prior to test
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #12	2013-01-23 15:44
MOT test number	716253023070
Result	✗ Failed
Notice	Under-trays fitted obscuring some underside components
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)
Fail	Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
Notice	Items removed from driver's view prior to test
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11**

2012-01-21 11:16

MOT test number

669451722039

Result

✓ Passed

- Notice** Rear brake discs worn, scored and pitted.
- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Notice** Tow ball/hitch not fitted at time of test
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)
- Notice** Front brake discs worn, scored and pitted.
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

MOT #10

2012-01-21 11:16

MOT test number

206341922047

Result

✗ Failed

- Notice** Rear brake discs worn, scored and pitted.
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Tow ball/hitch not fitted at time of test
- Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)
- Notice** Front brake discs worn, scored and pitted.
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)

**MOT #9** 2011-01-24 11:21**MOT test number** 867104721053**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2010-01-20 11:39**MOT test number** 584670520036**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2009-01-30 09:48**MOT test number** 634620639087**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2009-01-22 11:59**MOT test number** 901802429021**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #5** 2008-01-31 15:41**MOT test number** 574021638064**Result** ✓ Passed**MOT #4** 2008-01-31 09:15**MOT test number** 111951338493**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Offside Front brake disc slightly scored (3.5.1h)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #3** 2007-09-12 15:01**MOT test number** 890735857266**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Right hand steering rack knuckle has slight free play**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2006-09-19 14:59**MOT test number** 392442966449**Result** ✓ Passed



MOT #1	2006-09-16 11:01
MOT test number	494259656220
Result	✗ Failed
Fail	Offside Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Nearside Front Seat belt retracting mechanism defective (5.2.5b)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 Y203JKW
Plate since	2020-03-29
Current registration	 Y203JKW
Plate since	2020-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-07-20
Last registration	2019-10-14
Complete history	See info



Registration #1	2001-07-20	20 mi
Registration #2	2006-09-16	78.439 mi
Registration #3	2006-09-19	78.439 mi
Registration #4	2007-09-12	81.616 mi
Registration #5	2008-01-31	85.234 mi
Registration #6	2008-01-31	85.234 mi
Registration #7	2009-01-22	93.414 mi
Registration #8	2009-01-30	93.531 mi
Registration #9	2010-01-20	101.630 mi
Registration #10	2011-01-24	106.204 mi
Registration #11	2012-01-21	112.383 mi
Registration #12	2013-01-23	119.626 mi
Registration #13	2019-10-14	121.277 mi
Registration #14	2019-10-14	121.277 mi
Registration #15	2019-10-14	121.277 mi
Registration #16	2019-10-14	121.277 mi
Registration #17	2019-10-14	121.277 mi
Registration #18	2019-10-14	121.277 mi
Registration #19	2019-10-14	121.277 mi
Registration #20	2019-10-14	121.277 mi
Registration #21	2019-10-14	121.277 mi
Registration #22	2019-10-14	121.277 mi
Registration #23	2019-10-14	121.277 mi
Registration #24	2019-10-14	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1746 mm
Height	1498 mm
Length	4682 mm
Wheel base	2703 mm
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number

AVB068780