





report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI QUATTRO DPF S LINE
Colour	Silver
Year of manufacture	2011
Top speed	140 mph
0 - 100 km/h	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 kW / 143 HP / 170 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	145 g/km
CO2 label	F



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2022-12-13
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	6

MOT #9	2021-12-14 15:08
MOT test number	541119351561
Result	✓ Passed
Next expiry date	2022-12-13

MOT #8	2020-12-11 15:33
MOT test number	769088466732
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #7	2020-12-08 16:23
MOT test number	191629352279
Result	× Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Rear Rear fog lamp not working both switch straight off (4.5.1 (a) (ii))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 2/10



MOT #6 2019-06-11 16:35

MOT test number 126439072507

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

MOT test number

197126897169

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2017-01-04 15:15

 MOT test number
 711865763501

 Result
 ✓ Passed

CarCheck.co.uk page 3/10



MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner	history

For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2011-10-26
Last registration	2021-12-14
Complete history	See info



Registration #1	2011-10-26	20 mi
Registration #2	2014-10-13	29.887 mi
Registration #3	2017-01-04	33.831 mi
Registration #4	2017-12-23	43.441 mi
Registration #5	2018-12-17	45.400 mi
Registration #6		11.777 es
Registration #7		91.777 es
Registration #8		11.777 es
Registration #9		11.777 46

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4717 mm
Wheel base	2808 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	65 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 10/10

Number of axles 2

Engine number CAH 203629