



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE DCI N-TEC
Colour	Black
Year of manufacture	2011
Top speed	102 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.900 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	62.8 mpg
CO2 emission	110 g/km
CO2 label	B





MOT history

MOT expiry date	2024-06-10
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	41
Total items failed	1

MOT #15	2023-05-22 15:40
MOT test number	125102536962
Result	✓ Passed
Next expiry date	2024-06-10
Advice	Play in steering rack inner joint(s) Both sides
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #14	2023-05-22 10:01
MOT test number	383457815255
Result	✗ Failed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Offside Front Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i))
Advice	Play in steering rack inner joint(s) Both sides
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #13**

2022-05-19 09:58

MOT test number

299528143212

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12**

2022-05-17 11:28

MOT test number

569986850343

Result

✗ Failed

MAJOR Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**DANGEROUS** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**DANGEROUS** Offside Front Lower Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))**MAJOR** Bonnet cannot be secured in the closed position (3.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Front Brake disc significantly and obviously worn Both (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2021-06-11 13:11**MOT test number** 203449608589**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, but not excessively Both. (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Registration plate deteriorated but not likely to be misread Both. (0.1 (b))**Advice** Parking brake has slight reserve travel.**MOT #10** 2020-07-22 10:22**MOT test number** 108996957602**Result** ✓ Passed**MOT #9** 2019-07-31 14:50**MOT test number** 886698737808**Result** ✓ Passed**MOT #8** 2019-07-31 08:17**MOT test number** 862365873541**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #7** 2018-11-21 09:40**MOT test number** 637062229221**Result** ✓ Passed

**MOT #6** 2018-11-16 11:42**MOT test number** 976768441929**Result** ✗ Failed**MAJOR** Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))**MAJOR** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))**MOT #5** 2017-11-18 09:46**MOT test number** 642223676358**Result** ✓ Passed**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**Advice** Front Brake pad(s) wearing thin very low (3.5.1g)**MOT #4** 2017-11-18 09:46**MOT test number** 121418316201**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin very low (3.5.1g)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)**MOT #3** 2016-11-14 11:06**MOT test number** 245809720157**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2015-11-10 10:44
MOT test number	518989757599
Result	✓ Passed

MOT #1	2014-11-22 12:27
MOT test number	639726824379
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	BN61LKP
Plate since	2019-09-29
Current registration	BN61LKP
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-30
Last registration	2023-05-22
Complete history	See info



Registration #1	2011-09-30	26 mi
Registration #2	2014-11-22	22.210 mi
Registration #3	2015-11-10	26.309 mi
Registration #4	2016-11-14	32.899 mi
Registration #5	2017-11-18	39.449 mi
Registration #6	2017-11-18	39.449 mi
Registration #7	2018-11-16	46.931 mi
Registration #8	2018-11-21	47.209 mi
Registration #9	2019-05-22	55.277 mi
Registration #10	2019-05-22	55.277 mi
Registration #11	2019-05-22	55.277 mi
Registration #12	2019-05-22	55.277 mi
Registration #13	2019-05-22	55.277 mi
Registration #14	2019-05-22	55.277 mi
Registration #15	2019-05-22	55.277 mi
Registration #16	2019-05-22	55.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1690 mm
Height	1550 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1165 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	016953