



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVTI T SPIRIT
Colour	Blue
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	170 Nm at 4.800 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.2 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-09-21
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-02
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	30
Total items failed	10

MOT #23	2023-11-03 08:13
MOT test number	958248638773
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Corrosion rear inner sills
Advice	Front and rear suspension components corroded
Advice	Corrosion rear chassis

MOT #22	2023-10-26 15:43
MOT test number	659564349562
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Corrosion rear chassis
Advice	Corrosion rear inner sills
Advice	Front and rear suspension components corroded

**MOT #21** 2022-10-27 14:17**MOT test number** 460094853186**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers has slight external damage to the casing Corroded (5.3.2 (b))**MOT #20** 2021-11-02 17:14**MOT test number** 792024818300**Result** ✓ Passed**MOT #19** 2021-02-04 08:46**MOT test number** 333802530180**Result** ✓ Passed**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Near side front tyre on 3.0mm (205/55x16)**MOT #18** 2021-02-04 08:46**MOT test number** 956806800433**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Near side front tyre on 3.0mm (205/55x16)

**MOT #17** 2020-02-05 08:48**MOT test number** 645112296523**Result** ✓ Passed**Advice** 1 x rear exhaust mount broken**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #16** 2019-02-13 15:12**MOT test number** 251515489901**Result** ✓ Passed**MOT #15** 2019-02-12 13:41**MOT test number** 424720677748**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Exhaust has a major leak of exhaust gases middle (6.1.2 (a))**MOT #14** 2018-02-07 17:54**MOT test number** 980292022536**Result** ✓ Passed**MOT #13** 2018-02-07 08:39**MOT test number** 887988085241**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Brake pipe slightly corroded rear section of near side front to rear (3.6.B.2c)**Fail** Brake pipe excessively corroded rear section of off side front to rear (3.6.B.2c)

**MOT #12**

2017-01-31 09:25

MOT test number

300315551911

Result

✓ Passed

Advice

Rear Bonded suspension unit deteriorated but can function as intended both main bushes (2.4.F.3)

Advice

Exhaust rear silencer mounts corroded

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Parking brake lever has little reserve travel (3.1.6b)

MOT #11

2016-02-08 09:13

MOT test number

661753925035

Result

✓ Passed

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #10

2016-02-08 09:12

MOT test number

163018435814

Result

✗ Failed

Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

MOT #9

2015-02-14 11:28

MOT test number

115065845412

Result

✓ Passed

MOT #8

2014-02-05 11:56

MOT test number

439716834087

Result

✓ Passed

Advice

Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2013-01-25 11:08**MOT test number** 566335423027**Result** ✓ Passed**MOT #6** 2013-01-25 11:08**MOT test number** 149785323064**Result** ✗ Failed**Pass with rectification** Front Service brake application uneven across the axle (3.7.D.2b)**MOT #5** 2012-01-26 11:02**MOT test number** 198026522492**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Front brake discs worn**MOT #4** 2011-01-27 10:25**MOT test number** 936097221016**Result** ✓ Passed**Notice** Front wipers splitting**MOT #3** 2011-01-27 10:25**MOT test number** 759257521085**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Front wipers splitting**Pass with rectification** Nearside Headlamp aim too high (1.8)



MOT #2	2010-01-29 15:59
MOT test number	522439320051
Result	✓ Passed

MOT #1	2009-01-28 10:23
MOT test number	420758229047
Result	✓ Passed

- Notice** Nail in offside front tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YL55VBG
Plate since	2019-09-29
Current registration	YL55VBG
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-01-31
Last registration	2023-11-03
Complete history	See info



Registration #1	2006-01-31	27 mi
Registration #2	2009-01-28	18.886 mi
Registration #3	2010-01-29	25.230 mi
Registration #4	2011-01-27	30.780 mi
Registration #5	2012-01-26	35.545 mi
Registration #6	2013-01-25	40.343 mi
Registration #7	2014-02-05	46.017 mi
Registration #8	2015-02-14	53.903 mi
Registration #9	2016-02-08	61.114 mi
Registration #10	2016-02-08	61.114 mi
Registration #11	2017-01-31	68.681 mi
Registration #12	2018-02-07	74.091 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi
Registration #19	2019-05-29	75.377 mi
Registration #20	2019-05-29	75.377 mi
Registration #21	2019-05-29	75.377 mi
Registration #22	2019-05-29	75.377 mi
Registration #23	2019-05-29	75.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZE466915