



**SB67XKT**


report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC EDITION TDCI
Colour	Silver
Year of manufacture	2017
Top speed	112 mph
0 - 100 km/h	10.8 seconds
0 - 60 mph	12.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88.2 kW / 120 HP / 94 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A







Internet history

Entry 1

Date	2021-08-11
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-15
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	3
Total items failed	7

MOT #6	2023-09-08 09:26
MOT test number	626736940531
Result	✓ Passed
Next expiry date	2024-09-15

MOT #5	2022-09-14 15:50
MOT test number	706873916739
Result	✓ Passed

MOT #4	2022-09-14 11:05
MOT test number	180161792106
Result	✗ Failed

- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #3	2021-09-16 15:01
MOT test number	176756762146
Result	✓ Passed



MOT #2 2021-09-10 14:57

MOT test number 438961354182

Result ✗ Failed

- Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice TPMS lamp on amber
- Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #1 2020-12-30 08:47

MOT test number 234600774706

Result ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-12-31
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2017-12-31	20 mi
Registration #2	2020-12-30	34.933 mi
Registration #3	2021-09-10	40.267 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	82%
Pedestrian	72%
Safety systems	71%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2010 mm
Height	1469 mm
Length	4360 mm
Wheel base	2648 mm
Kerb weight	1264 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	HB30890