



General information

Make	MINI
Model	ROADSTER COOPER S
Colour	Red
Year of manufacture	2015
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	181 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2



Date	2023-09-19
Pictures	19
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-07-15
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-08-17
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	4

MOT #8	2023-08-17 13:36
MOT test number	141905967466
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7	2023-08-15 09:53
MOT test number	703109624936
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6	2022-08-18 11:50
MOT test number	149982014448
Result	✓ Passed

**MOT #5** 2022-05-11 08:51**MOT test number** 146315000192**Result** ✓ Passed**Advice** Slight runout on front brakes**Advice** Front tyres wearing low/ osf sidewall cut**MOT #4** 2020-08-25 15:21**MOT test number** 551029917922**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2019-07-11 11:46**MOT test number** 637454678123**Result** ✓ Passed**MOT #2** 2019-07-11 11:37**MOT test number** 697245888494**Result** ✗ Failed**Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**MOT #1** 2018-07-12 10:52**MOT test number** 718546444182**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 August 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-05-29
Last registration	2023-08-17
Complete history	See info



Registration #1	2015-05-29	8 mi
Registration #2	2018-07-12	8.126 mi
Registration #3	2019-07-11	10.074 mi
Registration #4	2019-07-11	10.074 mi
Registration #5	2020-08-25	12.671 mi
Registration #6	2022-05-11	16.176 mi
Registration #7	2023-08-17	16.176 mi
Registration #8	2023-08-17	16.176 mi
Registration #9	2023-08-17	16.176 mi
Registration #10	2023-08-17	16.176 mi
Registration #11	2023-08-17	16.176 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1683 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Number of axles	2
Engine number	A072J893