





report date: 2024-03-29

General information

Make	KIA
Model	STONIC FIRST EDITION
Colour	White
Year of manufacture	2018
Top speed	115 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

F	n	+	rv	,	2
드	ш	L	ΙV	,	_

Date	2022-01-09
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2022-01-08
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-03-20
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #5	2024-03-13 10:42
MOT test number	994390414904
Result	✓ Passed
Next expiry date	2025-03-20

MOT #4	2023-03-15 17:12
MOT test number	160022025545
Result	✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing perishing on inner wall and between tread pattern (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing perishing on inner wall and between tread pattern (5.2.3 (d) (ii))

MOT #3 2023-03-15 16:16

MOT test number 380554880074

Result X Failed

Advice Nearside Front Tyre slightly damaged/cracking or perishing perishing on inner wall and between tread pattern (5.2.3 (d) (ii))

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing perishing on inner wall and between tread pattern (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2		2022-02-23 08:12
MOT test	number	527384947090
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #1	2021-02-24 13:55
MOT test number	591983686012
Result	✓ Passed

CarCheck.co.uk page 4/11



LG18HZB report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	20 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



LG18HZB report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



LG18HZB report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK WE
Plate since	
	More info >

CarCheck.co.uk page 8/11



LG18HZB report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-21
Last registration	2024-03-13
Complete history	See info



Registration #1	2018-03-21	28 mi
Registration #2	2021-02-24	28.543 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Designation #0		

Registration #8

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	93%
Children	84%
Pedestrian	71%
Safety systems	59%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1520 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1278 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11