





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Blue
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

MOT #20		2023-03-30 13:38
MOT test	number	130615638258
Result		✓ Passed
Next expi	ry date	2024-03-29
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Chip a zone	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #19		2023-03-29 15:08
MOT test	number	876403574354
Result		× Failed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Of	fside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.	3 (g) (ii))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Chip a zone	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/15



report date: 2024-03-28

MOT #18 2022-03-12 09:08 **MOT** test number 544063875134 Result ✓ Passed **Advice** Rear Lower Gearbox mounting defective Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #17 2022-03-12 09:08 415409492127 **MOT test number** Result × Failed Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Front Exhaust has a minor leak of exhaust gases (6.1.2 (a)) **Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Rear Lower Gearbox mounting defective

MOT #16		2021-03-30 10:57
MOT test	number	209150677517
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/15



report date: 2024-03-28


MOT #15 2021-03-24 11:38 **MOT** test number 448027814998 Result **X** Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Fail Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i)) Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b)) Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i)) **Advice** Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14		2020-03-27 14:37
MOT test	number	893341023948
Result		✓ Passed
Advice	Offside Front Inner Play in steering rack inner joint(s)	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 5/15



report date: 2024-03-28



MOT #12		2019-03-07 11:59
MOT test	number	874135864305
Result		✓ Passed
Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view St	tone chip (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge And perishing (5.2	.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d)	(ii))

CarCheck.co.uk page 6/15



Advice

Fail

EX58CMO

report date: 2024-03-28

MOT #11 2019-03-06 12:18 **MOT** test number 271275296243 Result **X** Failed **Advice** Offside Front Tyre slightly damaged/cracking or perishing Perishing (5.2.3 (d) (ii)) Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Direction indicator not working (4.4.1 (a) (ii)) Fail **Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Minor Offside Front Windscreen damaged but not adversely affecting driver's view Stone chip (3.2 (a) (i))

MOT #10	2018-03-05 16:14
MOT test number	610803217714
Result	✓ Passed

Nearside Front Tyre worn close to legal limit/worn on edge And perishing (5.2.3 (e))

Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #9	2018-03-05	13:40
MOT tes	st number 27177791	.3501
Result	× F	ailed
Fail	Offside Registration plate lamp not working (1.1.C.1d)	
Fail	Stop lamp not working all (1.2.1b)	
Fail Nearside Front Lower Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)		

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #8		2017-03-06 12:27
MOT test	number	501466934529
Result		✓ Passed
MOT #7		2015-12-08 17:15
MOT test	number	570457367080
Result		✓ Passed
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Advice	Off and near side front brake discs show a lipped edge.	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front service brakes show imbalance of 12%.	

MOT #6	2015-12-08 15:00
MOT test number	162731715450
Result	X Failed
Fail Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)	
Fail Bonnet cannot be secured in the closed position (8.4.1)	
Advice Off and near side front brake discs show a lipped edge.	
Fail Offside Front Headlamp aim too high (1.8)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front service brakes show imbalance of 12%.	
Fail Bonnet retaining device insecure (8.4.2)	

CarCheck.co.uk page 8/15



report date: 2024-03-28

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

MOT test number

496313944308

Result

Pass with rectification Centre Stop lamp not working (1.2.1b)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2012-12-14 10:59

 MOT test number
 255059142313

 Result
 ✓ Passed

 MOT #1
 2011-08-30 16:34

 MOT test number
 928472441261

 Result
 ✓ Passed

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

\sim	1 1 1
Owner	nistory
O WILCI	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,

For how long did the current and previous owner(s) have this FORD? How many owners check it in the premium report and see all owner registrations. Download the full report		?

	More info >	
Plate changes	·	
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-09-01
Last registration	2023-03-30
Complete history	See info



Registration #1	2008-09-01	28 mi
Registration #2	2011-08-30	26.787 mi
Registration #3	2012-12-14	45.095 mi
Registration #4	2013-11-18	55.559 mi
Registration #5	2014-12-09	68.245 mi
Registration #6	2015-12-08	79.504 mi
Registration #7	2015-12-08	79.504 mi
Registration #8	2017-03-06	90.012 mi
Registration #9	2018-03-05	95.737 mi
Registration #10	2018-03-05	95.738 mi
Registration #11	2019-03-06	98.245 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		11.777 es

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 15/1

Number of axles 2

Engine number 8R43181