



GLIIOC

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T200 LR P/V
Colour	Blue
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	175 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-08-09
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	40
Total items failed	6

MOT #14	2023-07-31 16:34
MOT test number	487224697993
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13	2023-07-31 16:34
MOT test number	901762969515
Result	✗ Failed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12**

2022-07-22 08:38

MOT test number

132749775612

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases rear pipe (6.1.2 (a))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view zone a (3.2 (a) (i))**MOT #11**

2022-07-18 12:53

MOT test number

893809452259

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases rear pipe (6.1.2 (a))**Minor** Windscreen damaged but not adversely affecting driver's view zone a (3.2 (a) (i))**MOT #10**

2021-08-10 12:59

MOT test number

515119766122

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #9** 2020-07-10 13:06**MOT test number** 137030667566**Result** ✓ Passed**MOT #8** 2019-06-24 15:35**MOT test number** 866693934879**Result** ✓ Passed

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Fluid residue on fuel tank but no visible signs of leak at time of test.
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2018-07-17 06:59**MOT test number** 155319613617**Result** ✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #6** 2018-07-17 06:59**MOT test number** 747893310235**Result** ✗ Failed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #5** 2017-06-30 08:19**MOT test number** 928577857976**Result** ✓ Passed**MOT #4** 2016-06-27 15:35**MOT test number** 698826246784**Result** ✓ Passed**MOT #3** 2015-06-16 16:54**MOT test number** 215267065127**Result** ✓ Passed**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Items removed from driver's view prior to test**Notice** Light scratch on windscreen



MOT #2 2015-06-16 16:54

MOT test number 749527665126

Result ✗ Failed

Notice Items removed from driver's view prior to test

Notice Light scratch on windscreen

Pass with rectification Offside Rear Direction indicators incorrect colour (1.4.A.2f)

Notice Vehicle's internal headlight adjuster altered to recheck lights

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2014-05-30 12:48

MOT test number 675990254153

Result ✓ Passed

Advice Offside Front Anti-roll bar linkage has slight play in a pin bearing (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 August 2024

Tax status	Valid until 1 February
-------------------	------------------------

Days left	277
------------------	-----

MOT expiry date	9 August 2024
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-29
Last registration	2023-07-31
Complete history	See info



Registration #1	2011-06-29	10 mi
Registration #2	2014-05-30	33.900 mi
Registration #3	2015-06-16	47.485 mi
Registration #4	2016-06-27	58.417 mi
Registration #5	2017-06-30	69.424 mi
Registration #6	2018-07-17	80.820 mi
Registration #7	2018-07-17	80.820 mi
Registration #8	2019-06-29	91.227 mi
Registration #9	2019-06-29	91.227 mi
Registration #10	2019-06-29	91.227 mi
Registration #11	2019-06-29	91.227 mi
Registration #12	2019-06-29	91.227 mi
Registration #13	2019-06-29	91.227 mi
Registration #14	2019-06-29	91.227 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1392 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BD93214