





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX LX TDCI
Colour	Silver
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



Internet history

-		-		1
п	L	ΓV	,	т.

Entry 1	
Date	2021-10-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2023-08-17
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	28
Total items failed	7

MOT #19		2022-08-18 06:49
MOT test	number	865082933020
Result		✓ Passed
Next exp	iry date	2023-08-17
Advice	Nearside Front Inner Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Minor	Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3	.4 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed (1.1.14 (a) (ii))

MOT #18	2021-02-19 12:42
MOT test number	365880030845
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number

Result

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Inner Edge Worn (5.2.3 (e))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to legal limit/worn on edge Inner Edge Worn (5.2.3 (e))

MOT #16

MOT test number

139186088105

Result

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2018-03-16 11:34
MOT test number	915845089111
Result	✓ Passed

MOT #13	2018-03-16 11:29
MOT test number	603927599132
Result	✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2018-03-13 10:02

MOT test number 769114922209

Result X Failed

Fail Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

MOT #11 2017-03-21 09:18

MOT test number 379335113731

Result \(\sqrt{Passed} \)

MOT #10 2017-03-20 11:19

MOT test number 716977258563

Result X Failed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2016-03-03 17:07

MOT test number 809868659557

Result \(\sqrt{Passed} \)

Advice Child seat fitted at rears

Advice Trailing arm rubber bush deteriorated but not resulting in excessive movement both sides rear

(2.4.G.2)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8 2016-03-03 10:38

MOT test number 118438543858

Result X Failed

Advice Trailing arm rubber bush deteriorated but not resulting in excessive movement both sides rear (2.4.G.2)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Rear Exhaust has a major leak of exhaust gases missing (7.1.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Child seat fitted at rears

MOT #7 2015-03-23 13:59

MOT test number 585942085013

MOT #6 2015-03-23 09:52

MOT test number 177752385085

Result X Failed

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

MOT #5 2014-03-21 16:16

MOT test number 618530084021

Result \rightarrow Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2014-03-20 10:23

MOT test number 489159574060

Result × Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3 2013-03-07 15:31 **MOT test number** 138706863446 ✓ Passed Result MOT #2 2012-03-14 11:00 **MOT test number** 429354672024 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Offside rear tyre worn low Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1		2011-03-08 10:28
MOT test	number	708337461043
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	17 August 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history

		_
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		

	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-25
Last registration	2022-08-18
Complete history	See info



Registration #1	2008-03-25	27 mi
Registration #2	2011-03-08	42.768 mi
Registration #3	2012-03-14	59.595 mi
Registration #4	2013-03-07	75.661 mi
Registration #5	2014-03-20	92.130 mi
Registration #6	2014-03-21	92.130 mi
Registration #7	2015-03-23	105.722 mi
Registration #8	2015-03-23	105.722 mi
Registration #9	2016-03-03	121.085 mi
Registration #10	2016-03-03	121.085 mi
Registration #11	2017-03-20	132.264 mi
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 esi
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.707 es
Registration #20		11.777 es
Registration #21		11.777 esi

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/1

Number of axles2Engine number8R41969