



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D R-DESIGN
Colour	Black
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-29
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-20
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	30
Total items failed	18

MOT #19	2024-01-05 16:23
MOT test number	502756357871
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge/ cuts (5.2.3 (e))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone, rear bush (5.3.4 (a) (i))

**MOT #18**

2024-01-03 10:54

**MOT test number**

410258358035

**Result****✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald on inner edge/ cuts (5.2.3 (e))**Fail** Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone, rear bush (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald on inner (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cracking (5.2.3 (d) (i))**Fail** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))**Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #17**

2023-01-05 17:03

**MOT test number**

817077989350

**Result****✓ Passed****Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Offside Rear Inner Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2023-01-05 12:11

**MOT test number**

282479589602

**Result****✗ Failed****Fail**

Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))

**Minor**

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail**

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Minor**

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Fail**

Offside Front Suspension arm pin or bush excessively worn rear bush on suspension arm. (5.3.4 (a) (i))

**Minor**

Offside Rear Inner Position lamp light intensity obviously reduced (4.2.3 (a) (i))

**MOT #15**

2022-01-11 17:25

**MOT test number**

360853962822

**Result****✓ Passed****MOT #14**

2022-01-10 11:34

**MOT test number**

182302183596

**Result****✗ Failed****Advice**

Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Offside Front Suspension arm pin or bush excessively worn rear bush on suspension arm. (5.3.4 (a) (i))

**Advice**

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice**

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail**

Offside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

**Advice**

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13** 2021-01-21 17:18**MOT test number** 576622010177**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-12-19 12:55**MOT test number** 616882847921**Result** ✓ Passed**MOT #11** 2019-12-19 10:54**MOT test number** 139773005340**Result** ✗ Failed**Fail** Rear Exhaust system insecure mounting corroded and broken off (6.1.2 (a))**Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))**MOT #10** 2019-01-16 09:20**MOT test number** 489333391052**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front both front tryres wearing inner edges**MOT #9** 2017-12-21 10:28**MOT test number** 168365059636**Result** ✓ Passed**MOT #8** 2016-12-29 14:46**MOT test number** 688343094801**Result** ✓ Passed

**MOT #7** 2016-12-29 14:45**MOT test number** 876883336637**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2015-12-22 13:18**MOT test number** 387786764200**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #5** 2014-12-30 14:04**MOT test number** 459364064379**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2014-12-30 14:04**MOT test number** 449504264392**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #3** 2014-01-10 16:15**MOT test number** 827180814029**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-01-17 10:33
MOT test number	698647213053
Result	✓ Passed

MOT #1	2013-01-17 09:58
MOT test number	246367613048
Result	✗ Failed
<div><div>Fail</div> Nearside Front Suspension arm attachment bracket/mounting bolt missing (2.4.G.1)</div>	
<div><div>Pass with rectification</div> Front Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Fail</div> Offside Front Suspension arm attachment bracket/mounting bolt missing (2.4.G.1)</div>	
<div><div>Fail</div> Offside Front Front position lamp(s) not working (1.1.A.3b)</div>	





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
20 January 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	20 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-01-18
Last registration	2024-01-05
Complete history	<a href="#">See info</a>



Registration #1	2010-01-18	20 mi
Registration #2	2013-01-17	55.133 mi
Registration #3	2013-01-17	55.133 mi
Registration #4	2014-01-10	72.161 mi
Registration #5	2014-12-30	89.510 mi
Registration #6	2015-12-22	107.903 mi
Registration #7	2016-12-29	126.334 mi
Registration #8	2016-12-29	126.334 mi
Registration #9	2017-12-21	144.625 mi
Registration #10	2019-01-16	145.289 mi
Registration #11	2019-01-16	145.289 mi
Registration #12	2019-01-16	145.289 mi
Registration #13	2019-01-16	145.289 mi
Registration #14	2019-01-16	145.289 mi
Registration #15	2019-01-16	145.289 mi
Registration #16	2019-01-16	145.289 mi
Registration #17	2019-01-16	145.289 mi
Registration #18	2019-01-16	145.289 mi
Registration #19	2019-01-16	145.289 mi
Registration #20	2019-01-16	145.289 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	746796