



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SE-L NAV
Colour	Silver
Year of manufacture	2018
Top speed	131 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	107 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-01
Pictures	7
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-27
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #6	2024-02-28 15:53
MOT test number	857278546561
Result	✓ Passed
Next expiry date	2025-02-27
Advice	Offside Front Anti-roll bar linkage ball joint has slight play Knocking (5.3.4 (a) (i))

MOT #5	2024-02-14 15:04
MOT test number	122083494746
Result	✗ Failed
MAJOR	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
Advice	Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
MAJOR	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
MAJOR	Offside Rear Road wheel fixing missing (5.2.1 (a) (i))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play knocking (5.3.4 (a) (i))
MAJOR	Offside Front Service brake excessively fluctuating (1.2.1 (e))
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))

**MOT #4** 2023-01-06 11:13**MOT test number** 564966741178**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin inner (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2021-12-30 14:58**MOT test number** 681466907566**Result** ✓ Passed**MOT #2** 2021-12-30 14:58**MOT test number** 931657499555**Result** ✗ Failed**Pass with rectification** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #1** 2020-11-27 11:12**MOT test number** 290970999969**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
27 February 2025

Tax status	Valid until 1 November
Days left	187
MOT expiry date	27 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-03-29
Last registration	2024-02-28
Complete history	See info



Registration #1	2018-03-29	7 mi
Registration #2	2020-11-27	19.431 mi
Registration #3	2021-12-30	46.529 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4865 mm
Wheel base	2830 mm
Kerb weight	1405 kg
Max. allowed weight	2055 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	SH 30803742