



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS INDIVIDUAL FSI DSG 200
Colour	Black
Year of manufacture	2010
Top speed	142 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	280 Nm at 5.000 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.5 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-06-19
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-18
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	11
Total items failed	3

MOT #13	2023-07-10 13:27
MOT test number	958801844931
Result	✓ Passed
Next expiry date	2024-07-18

MOT #12	2022-07-01 08:54
MOT test number	767266389660
Result	✓ Passed
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #11	2022-07-01 08:54
MOT test number	679283574010
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #10	2021-07-19 16:37
MOT test number	379261349262
Result	✓ Passed

**MOT #9** 2020-08-29 10:24**MOT test number** 522055111794**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing outer wall damaged (5.2.3 (d) (ii))**MOT #8** 2019-08-23 11:48**MOT test number** 283684504415**Result** ✓ Passed**MOT #7** 2018-07-30 14:33**MOT test number** 352863858396**Result** ✓ Passed**MOT #6** 2018-07-30 12:50**MOT test number** 107858958647**Result** ✗ Failed**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure inner / outer walls (5.2.3 (d) (i))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (i))**MOT #5** 2017-07-19 16:10**MOT test number** 531285339069**Result** ✓ Passed**Advice** Undertrays fitted obscuring some underside components**Advice** Front offside tyre walls small splits**Advice** Front nearside tyre inner edge slightly worn**Advice** Front brake pads worn

**MOT #4** 2016-07-19 16:14**MOT test number** 516636034697**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)**Advice** Offside Rear Road wheel with a slightly distorted bead rim inner rim (4.2.A.1a)**MOT #3** 2015-07-22 10:02**MOT test number** 508863305213**Result** ✓ Passed**MOT #2** 2014-06-09 13:50**MOT test number** 148810064189**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-06-04 12:32**MOT test number** 205265653462**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
18 July 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	18 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-26
Last registration	2023-07-10
Complete history	See info



Registration #1	2010-06-26	7 mi
Registration #2	2013-06-04	25.364 mi
Registration #3	2014-06-09	41.745 mi
Registration #4	2015-07-22	57.794 mi
Registration #5	2016-07-19	61.274 mi
Registration #6	2017-07-19	65.177 mi
Registration #7	2018-07-30	68.740 mi
Registration #8	2018-07-30	68.748 mi
Registration #9	2019-06-26	68.748 mi
Registration #10	2019-06-26	68.748 mi
Registration #11	2019-06-26	68.748 mi
Registration #12	2019-06-26	68.748 mi
Registration #13	2019-06-26	68.748 mi
Registration #14	2019-06-26	68.748 mi
Registration #15	2019-06-26	68.748 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1557 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CCZ038515