





report date: 2024-03-29

General information

| Make | PEUGEOT |
|---------------------|-----------------------------|
| Model | EXPERT HDI TEPEE COMFORT L1 |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 96 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 98 BHP |
|-------------------------|---------------------|
| Max. torque | 260 Nm at 1.500 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 41.5 mpg |
| CO2 emission | 179 g/km |
| CO2 label | I |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 2

Date 2021-11-10

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

Entry 1

| Date | 2021-08-27 |
|------|------------|
| | |

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-01-18 |
|--------------------|------------|
| MOT pass rate | 60 % |
| MOT passed | 6 |
| Failed MOT tests | 4 |
| Total advice items | 20 |
| Total items failed | 3 |

| MOT #10 | 2021-08-20 09:51 |
|------------------|------------------|
| MOT test number | 706057491696 |
| Result | ✓ Passed |
| Next expiry date | 2022-09-08 |

| MO1 #9 | 2021-08-09 13:43 |
|-----------------|------------------|
| MOT test number | 596279641409 |
| Result | × Failed |

MAJOR Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

| MOT #8 | 2020-09-09 10:11 |
|--|------------------|
| MOT test number | 123237870256 |
| Result | ✓ Passed |
| Minor Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

| MOT #7 | | 2020-09-09 10:11 |
|-------------------------|--|------------------|
| MOT test number | | 345594069636 |
| Result | | × Failed |
| Pass with rectification | Offside Headlamp aim too high (4.1.2 (a)) | |
| Minor Offside Windscree | en damaged but not adversely affecting driver's view (3.2 (a) (i)) | |

CarCheck.co.uk page 3/12



Advice

WF63KHW

report date: 2024-03-29

MOT #6

MOT test number

Result

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Offside Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-05-09 11:14 **MOT** test number 334411254511 Result × Failed **MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) **DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) **MAJOR** Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

 MOT #4
 2018-06-21 15:54

 MOT test number
 105387866956

 Result
 ✓ Passed

MOT #3

MOT test number

Result

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a))


Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29



| 2016-08-16 08:35 |
|------------------|
| 445076624943 |
| ✓ Passed |
| |
| |

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 18 January 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



WF63KHW
report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

WF63KHW

report date: 2024-03-29

| For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEU have? Check it in the premium report and see all owner registrations. Download the full report here . | JGEOT |
|--|-------|
| | |
| THE PERSON NAMED IN COLUMN TO THE PE | |
| | |
| ************* | |
| | |
| THE PERSON NAMED IN COLUMN TO THE PE | |
| | |
| | |
| | |

Plate changes

| See in this check if this PEUGEOT had different number plates. | |
|--|---------|
| Number of plates | |
| Current registration | OK SILE |
| Plate since | |
| Current registration | UK UK |
| Plate since | |

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| 011.1.6. | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-10-07 |
| Last registration | 2021-08-20 |
| Complete history | See info |



| Registration #1 | 2013-10-07 | 28 mi |
|------------------|------------|-----------|
| Registration #2 | 2016-08-16 | 39.582 mi |
| Registration #3 | 2017-07-31 | 56.327 mi |
| Registration #4 | 2018-06-21 | 69.197 mi |
| Registration #5 | 2018-06-21 | 69.197 mi |
| Registration #6 | 2019-05-09 | 81.928 mi |
| Registration #7 | 2019-05-09 | 81.928 mi |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 0.00 44 |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 0.00 44 |
| Registration #13 | | 10.777 au |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | *** |
|----------------|-----------------|
| Adult | 59% |
| Children | 86% |
| Pedestrian | 26% |
| Safety systems | 26% |
| Overall rating | 54% |
| Video | see crash video |



Dimensions & weight

| Width | 2176 mm |
|---------------------|---------|
| Height | 1934 mm |
| Length | 4806 mm |
| Max. allowed weight | 2780 kg |

Additional information

| Number of seats | 4 |
|-----------------|-------------|
| Number of axles | 2 |
| Engine number | DYZG4057292 |

CarCheck.co.uk page 12/12