





## General information

Make	MERCEDES
Model	VITO 109 CDI COMPACT P/V
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	88 BHP
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel

225+





Internet history	
Entry 1	
Date	2021-10-17
Pictures	0
Listing price	View report

source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-22
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	61
Total items failed	7

MOT #14		2024-03-08 12:24
MOT test	number	623825728830
Result		🗸 Passed
Next exp	iry date	2025-03-22
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear TOWING SOCKET WORKING BUT DIDNT AT FIRST SUSPECT CORROSION I	IN PLUG
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Minor</b> (g) (i))	Nearside Rear Inner Drive shaft joint constant velocity boot severely deteriorate	ted CRACKING (6.1.7
Advice light inter	Offside Front Position lamp has a product on the lens or light source but not a sity (4.2.3 (b) (ii))	adversely affecting
Advice	Rear Coil spring corroded BOTH REAR COIL SPRINGS (5.3.1 (b) (i))	
Advice	Nearside Rear LENS CRACKED	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor (i))	Offside Front Windscreen damaged but not adversely affecting driver's view S	TONE CHIP (3.2 (a)
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Central Front Child Seat fitted not allowing full inspection of adult belt	
<b>Minor</b> (g) (i))	Offside Rear Inner Drive shaft joint constant velocity boot severely deteriorate	d CRACKING (6.1.7



W	0	8	Μ	Ζ	U
rep	ort	dat	<b>e:</b> 20	24-0	3-29

MOT #13		2023-03-23 17:49
MOT test	number	154270497654
Result		✓ Passed
MOT #12		2022-01-14 12:00
MOT test	number	303336137984
Result		✓ Passed
Advice	Nearside Rear light lense has a crack in it	
Advice	Chip in windscreen	
MOT #11		2019-03-05 16:39
MOT test	number	676919677134
Result		Passed
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front outer sidewall damaged-not to cord	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5	5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Items removed from driver's view prior to test	
Advice	Nearside Front outer sidewall damaged-not to cord	
Advice	Oil leak, but not excessive rear of engine (8.4.1 (a) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #10	2018-03-21 11:14
MOT test number	620890777992
Result	✓ Passed



LW08MZU
report date: 2024-03-29

MOT #9		2017-03-16 12:45
MOT test	number	549361664305
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Oil leak	
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5	.A.1c)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.3	1i)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Nail in tyre	
Advice	Nearside Front Macpherson strut has slight movement at the upper attachment (2	.5.A.1c)
Advice	Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)	
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	)





MOT #8	2017-03-16 12:45		
MOT test number	863773836746		
Result	× Failed		
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Advice Oil leak			
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)		
Advice Nearside Rear b	rake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Offside Front Ma	acpherson strut has slight movement at the upper attachment (2.5.A.1c)		
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)			
Pass with rectification	Brake pedal anti-slip provision worn smooth (3.3.A.1b)		
Advice Offside Front Na	il in tyre		
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)		
Advice Nearside Front	Macpherson strut has slight movement at the upper attachment (2.5.A.1c)		
Advice Offside Rear bra	ke disc worn, pitted or scored, but not seriously weakened (3.5.1i)		
Advice Nearside Rear re	eflector slightly damaged but function not impaired (1.5.1c)		
Advice Offside Front Br	ake pad(s) wearing thin (3.5.1g)		



W	0	8	Μ	Ζ	U
rep	ort	dat	<b>e:</b> 20	24-0	3-29

MOT #7		2014-07-31 10:09
MOT test	number	858572314212
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Upper Coil spring mounting damaged but not seriously weaken	ned (2.4.C.3c)
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside coil spring worn (2.4.C.1b)	
Advice	Nearside Rear Lower Coil spring mounting damaged but not seriously weaken	ned (2.4.C.3c)

MOT #6		2014-07-31 10:09
MOT test	number	385972914475
Result		🗙 Failed
Pass wit	th rectification Rear fog lamp not working (1.3.2b)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice Nearside Rear Upper Coil spring mounting damaged but not seriously weakened (2.4.C.3c)		
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside coil spring worn (2.4.C.1b)	
Advice	Nearside Rear Lower Coil spring mounting damaged but not serious	ly weakened (2.4.C.3c)

MOT #5		2013-07-08 17:06
MOT test	number	238369283194
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	



W08MZU
report date: 2024-03-29

MOT #4		2013-07-08 17:06
MOT test number		728359183183
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too high (1.8)	
Advice Offside Rear Tyr	e worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Advice Front Brake pad	(s) wearing thin (3.5.1g)	

MOT #3		2012-08-23 12:39
MOT test i	number	489076132239
Result		✓ Passed
Advice	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8	3.1.2a)


MOT #2	2011-08-17 14:58
MOT test number	348099621491
Result	✓ Passed
MOT #1	2010-08-19 16:16
MOT test number	251061830282
Result	✓ Passed

....

Notice Parking brake in need of adjustment!!!!



Tax & MOT check







### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Date	
Category	AMPL
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
**********	
NULLESS CONTRACTOR CONTRA	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	
Current registration	
Plate since	
Correct registration	
Plate since	
	More info >





### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-08-19
Last registration	2024-03-08
Complete history	See info



Registration #1	2008-08-19	16 mi
Registration #2	2010-08-19	42.552 mi
Registration #3	2011-08-17	58.436 mi
Registration #4	2012-08-23	80.359 mi
Registration #5	2013-07-08	98.675 mi
Registration #6	2014-07-31	121.464 mi
Registration #7	2017-03-16	128.368 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Devictuation #12		
Registration #13		11.777 mil

More info >





Safety ratings

NCAP rating

Video

see crash video



Additional information	
Fuel tank capacity	75 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Engine number	64698051713889