



PEUGEOT



BG06ENH


report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 URBAN
Colour	Yellow
Year of manufacture	2006
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 2

Date	2021-07-10
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-06
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	56
Total items failed	3

MOT #19 2023-06-07 10:30

MOT test number 655213949738

Result ✓ Passed

Next expiry date 2024-06-06

- Advice** Offside Front Lower Suspension arm ball joint has slight play Borderline (5.3.4 (a) (i))
- Advice** Security of exhaust heatshield, affixed to fuel tank, cannot be removed
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside rear parking brake efficiency low in comparison to nearside rear
- Advice** Parking brake efficiency only just met. it would appear that the braking system requires adjustment or repair.
- Advice** Brake pipe corroded, covered in grease or other material Nearside front to rear MAIN (1.1.11 (c))
- Advice** Parking brake lever has limited reserve travel

MOT #18 2022-06-07 13:00

MOT test number 362436750125

Result ✓ Passed

**MOT #17** 2022-06-07 08:42**MOT test number** 195024889691**Result** ✗ Failed**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #16** 2021-05-11 15:41**MOT test number** 467186961226**Result** ✓ Passed**MOT #15** 2021-05-11 12:22**MOT test number** 381306689280**Result** ✗ Failed**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2019-04-17 16:08**MOT test number** 949649890114**Result** ✓ Passed**Advice** Handbrake travel**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Minor** Hazard warning switch faulty (4.4.2 (a) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2019-04-15 10:27

**MOT test number**

654329705267

**Result****✗ Failed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))
- MAJOR** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Handbrake travel
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Minor** Hazard warning switch faulty (4.4.2 (a) (i))
- MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #12**

2018-04-13 13:59

**MOT test number**

804991097465

**Result**

✓ Passed

- Advice** Underbody corrosion
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement link (2.4.G.2)
- Advice** Central Front exhaust corroded
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement link (2.4.G.2)
- Advice** All 4 tyre cracking in-between tread
- Advice** Front Exhaust has a minor leak of exhaust gases manifold (7.1.2)

**MOT #11**

2018-04-09 09:30

**MOT test number**

957623397199

**Result**

✗ Failed

- Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Central Front exhaust corroded
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement link (2.4.G.2)
- Advice** All 4 tyre cracking in-between tread
- Advice** Front Exhaust has a minor leak of exhaust gases manifold (7.1.2)
- Fail** Horn not working (1.6.2a)
- Advice** Underbody corrosion
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement link (2.4.G.2)

**MOT #10** 2017-04-08 11:48**MOT test number** 800760578904**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #9** 2017-04-08 11:48**MOT test number** 532610552023**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2016-04-16 08:55**MOT test number** 676303260708**Result** ✓ Passed**MOT #7** 2015-04-18 10:38**MOT test number** 238128605410**Result** ✓ Passed**MOT #6** 2014-04-12 11:53**MOT test number** 207922204152**Result** ✓ Passed**MOT #5** 2013-04-18 09:51**MOT test number** 266938703466**Result** ✓ Passed**Advice** Nearside Inner Front Road wheel slightly damaged (4.2.A.1a)



MOT #4	2012-04-21 09:09
MOT test number	348802712100
Result	✓ Passed
Advice	Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Notice	Exhaust system corroded
Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
Advice	Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3	2011-04-16 09:00
MOT test number	938666801168
Result	✓ Passed

MOT #2	2010-04-22 13:15
MOT test number	110702110111
Result	✓ Passed

MOT #1	2009-04-29 16:37
MOT test number	511409319122
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
6 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	6 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-04-29
Last registration	2023-06-07
Complete history	<a href="#">See info</a>



Registration #1	2006-04-29	18 mi
Registration #2	2009-04-29	33.919 mi
Registration #3	2010-04-22	41.689 mi
Registration #4	2011-04-16	45.507 mi
Registration #5	2012-04-21	51.321 mi
Registration #6	2013-04-18	57.415 mi
Registration #7	2014-04-12	61.227 mi
Registration #8	2015-04-18	63.970 mi
Registration #9	2016-04-16	66.652 mi
Registration #10	2017-04-08	69.837 mi
Registration #11	2017-04-08	69.837 mi
Registration #12	2018-04-08	71.277 mi
Registration #13	2018-04-08	71.277 mi
Registration #14	2018-04-08	71.277 mi
Registration #15	2018-04-08	71.277 mi
Registration #16	2018-04-08	71.277 mi
Registration #17	2018-04-08	71.277 mi
Registration #18	2018-04-08	71.277 mi
Registration #19	2018-04-08	71.277 mi
Registration #20	2018-04-08	71.277 mi
Registration #21	2018-04-08	71.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1465 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	825 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	5232018