




report date: 2024-03-29

General information

Make	NISSAN
Model	MICRA VISIA
Colour	Red
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





## Internet history

### Entry 1

Date	2021-01-21
Pictures	36
Listing price	<a href="#">View report</a>



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2025-02-11
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	0

**MOT #9** 2024-02-08 09:39

**MOT test number** 200337735891

**Result** ✓ Passed

**Next expiry date** 2025-02-11

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2023-02-10 12:57

**MOT test number** 371749259830

**Result** ✓ Passed

**MOT #7** 2023-02-09 16:54

**MOT test number** 861029717016

**Result** ✗ Failed

- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #6** 2022-02-09 14:37

**MOT test number** 607757789556

**Result** ✓ Passed



**MOT #5** 2021-02-12 16:56

**MOT test number** 321799955204

**Result** ✓ Passed

**MOT #4** 2021-01-29 15:10

**MOT test number** 363842267953

**Result** ✗ Failed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush de bonding (5.3.4 (a) (i))

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush de bonding (5.3.4 (a) (i))

**MOT #3** 2019-06-11 13:27

**MOT test number** 949311795017

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush debonding (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush debonding (5.3.4 (a) (i))

**MOT #2** 2018-06-11 09:09

**MOT test number** 325379743959

**Result** ✓ Passed

**MOT #1** 2017-06-07 13:52

**MOT test number** 620407775086

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
11 February 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	11 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



## Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>AV14XSU</b>
Plate since	2019-03-29
Current registration	<b>AV14XSU</b>
Plate since	2019-03-29

More info >



**Finance check**

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled. If not, and you buy this NISSAN then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this NISSAN is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	11
<b>First mileage registration</b>	2014-06-30
<b>Last registration</b>	2024-02-08
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2014-06-30	25 mi
<b>Registration #2</b>	2017-06-07	8.517 mi
<b>Registration #3</b>	2018-06-11	10.083 mi
<b>Registration #4</b>	2019-06-11	11.907 mi
<b>Registration #5</b>	2020-06-07	13.377 mi
<b>Registration #6</b>	2021-01-29	13.451 mi
<b>Registration #7</b>	2022-06-07	15.277 mi
<b>Registration #8</b>	2023-06-07	15.277 mi
<b>Registration #9</b>	2023-06-07	15.277 mi
<b>Registration #10</b>	2023-06-07	15.277 mi
<b>Registration #11</b>	2024-02-08	15.277 mi

[More info >](#)



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

780147B