



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Grey
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	J





Internet history

Entry 2

Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-08-30
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-21
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	42
Total items failed	4

MOT #17	2023-11-13 16:11
MOT test number	693682389419
Result	✓ Passed
Next expiry date	2024-11-21

MOT #16	2023-11-10 14:39
MOT test number	483979256405
Result	✗ Failed
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15	2022-11-17 14:41
MOT test number	472242624885
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-11-15 09:21**MOT test number** 289167628041**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Nearside Front road wheel marked 'rear only' fitted**Advice** Gearbox undertray broken**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Knock from steering column**MOT #13** 2021-11-15 09:21**MOT test number** 453579126716**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Knock from steering column**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Front road wheel marked 'rear only' fitted**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Gearbox undertray broken**MOT #12** 2020-11-13 09:55**MOT test number** 861047084909**Result** ✓ Passed**MOT #11** 2019-11-05 09:50**MOT test number** 980382921642**Result** ✓ Passed

**MOT #10** 2018-11-05 09:15**MOT test number** 146046669381**Result** ✓ Passed**MOT #9** 2017-11-07 13:05**MOT test number** 870867094919**Result** ✓ Passed

- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Intermitant knock from colume area.
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front wiper blades wearing, attention soon.
- Advice** Offside Front Upper Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)

MOT #8 2017-11-07 11:02**MOT test number** 843694971809**Result** ✗ Failed

- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Front wiper blades wearing, attention soon.
- Advice** Offside Front Upper Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)
- Advice** Front tyres both scrubbing bad on inner edges. Attention soon.
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Intermitant knock from colume area.

**MOT #7** 2016-10-24 09:58**MOT test number** 314635178208**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #6** 2015-10-29 11:17**MOT test number** 267743332258**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Both wiper blades wearing.**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear coil spring corroded at bottom. (2.4.C.1b)**Advice** Engine cover & under trays fitted at time of test.**MOT #5** 2014-11-11 14:12**MOT test number** 819385214339**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil low**Notice** Slight knocking from behind steering wheel**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under tray damaged**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2013-11-11 10:27**MOT test number** 506165013379**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Both front tyres scrubbing out on edges, perishing on both sidewalls and close to legal limit**MOT #3** 2012-10-23 11:14**MOT test number** 115387992258**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-10-24 12:59**MOT test number** 946187291247**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1** 2010-11-22 15:17**MOT test number** 184936420311**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 November 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-15
Last registration	2023-11-13
Complete history	See info



Registration #1	2007-03-15	25 mi
Registration #2	2010-11-22	36.974 mi
Registration #3	2011-10-24	45.516 mi
Registration #4	2012-10-23	52.861 mi
Registration #5	2013-11-11	57.434 mi
Registration #6	2014-11-11	63.355 mi
Registration #7	2015-10-29	68.725 mi
Registration #8	2016-10-24	73.633 mi
Registration #9	2017-11-07	78.312 mi
Registration #10	2017-11-07	78.315 mi
Registration #11	2019-05-29	79.377 mi
Registration #12	2019-05-29	79.377 mi
Registration #13	2019-05-29	79.377 mi
Registration #14	2019-05-29	79.377 mi
Registration #15	2019-05-29	79.377 mi
Registration #16	2019-05-29	79.377 mi
Registration #17	2019-05-29	79.377 mi
Registration #18	2019-05-29	79.377 mi
Registration #19	2019-05-29	79.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040446156