



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	AGILA SXI 16V TWINPORT
Colour	Silver
Year of manufacture	2005
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.229 cc
Cylinders	4
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	48.7 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-09-20
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2023-11-23
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #17	2022-11-16 16:39
MOT test number	683183539275
Result	✓ Passed
Next expiry date	2023-11-23
Advice	Rear Wheel bearing slightly noisy both (5.1.3 (b) (i))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #16	2021-11-24 11:21
MOT test number	429265136925
Result	✓ Passed
Advice	Nearside Front Macpherson strut ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2020-11-03 13:50
MOT test number	557255431728
Result	✓ Passed
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #14** 2019-02-16 12:24**MOT test number** 114933845996**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #13** 2019-02-12 12:33**MOT test number** 293710872193**Result** ✗ Failed**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**MOT #12** 2018-02-17 12:52**MOT test number** 807143882085**Result** ✓ Passed**MOT #11** 2017-02-18 12:15**MOT test number** 268686375171**Result** ✓ Passed**MOT #10** 2016-02-13 11:29**MOT test number** 494654754471**Result** ✓ Passed**MOT #9** 2015-02-07 10:32**MOT test number** 855738035022**Result** ✓ Passed

**MOT #8** 2014-01-29 09:13**MOT test number** 226179924006**Result** ✓ Passed**MOT #7** 2013-02-12 11:32**MOT test number** 919833443077**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2012-02-21 10:53**MOT test number** 387582052026**Result** ✓ Passed**MOT #5** 2011-08-02 09:04**MOT test number** 267834811273**Result** ✓ Passed**MOT #4** 2011-08-01 13:51**MOT test number** 589763411246**Result** ✗ Failed

- Fail** Front Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)

**MOT #3** 2011-04-07 09:02**MOT test number** 145417691044**Result** ✓ Passed



MOT #2	2009-11-24 14:01
MOT test number	413868629498
Result	✓ Passed
MOT #1	2008-12-16 09:44
MOT test number	752601758331
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
9 June 2023

X

MOT

Expired:  
23 November 2023

Tax status	Expired at 9 June 2023
Days left	325 days too late
MOT expiry date	23 November 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	YC550DK
Plate since	2019-06-29
Current registration	YC550DK
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-11-11
Last registration	2022-11-16
Complete history	<a href="#">See info</a>



Registration #1	2005-11-11	29 mi
Registration #2	2008-12-16	11.019 mi
Registration #3	2009-11-24	15.670 mi
Registration #4	2011-04-07	18.624 mi
Registration #5	2011-08-01	20.490 mi
Registration #6	2011-08-02	20.490 mi
Registration #7	2012-02-21	23.134 mi
Registration #8	2013-02-12	28.940 mi
Registration #9	2014-01-29	32.484 mi
Registration #10	2015-02-07	34.311 mi
Registration #11	2015-05-20	35.377 mi
Registration #12	2015-05-20	35.377 mi
Registration #13	2015-05-20	35.377 mi
Registration #14	2015-05-20	35.377 mi
Registration #15	2015-05-20	35.377 mi
Registration #16	2015-05-20	35.377 mi
Registration #17	2015-05-20	35.377 mi
Registration #18	2015-05-20	35.377 mi
Registration #19	2015-05-20	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3839 mm
Wheel base	2491 mm
Kerb weight	979 kg
Max. allowed weight	1430 kg

Additional information

Fuel tank capacity	44 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Engine number	19EJ8321